## **HOBBS OCD**

## State of New Mexico

BRADENHEAD TEST REPORT

## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

APR 2 4 2019

## **RECEIVED**

Operator Name Chevron Midcontinent, LP								
Property Name						1000	,	Well No
Central Vacuum Unit								194
* Surface Location								
	Naship Runge		Feet fi	roni N/S	Line	Feet From	EAV Line	LCC County
Well Status								
TA'D Well SHUT-IN			INJEC	TOR	PRO	ODUCER		DATE
YES (10)	VES	(6)	(XI)	8WD	OII.	GAS	3/	19/19
OBSERVED DATA								
	(A)Surf-Interm	(B)Intern	瑶[]	(C)Inte	<u>rm(2)</u>	(D))*rod	(205	(E)Tuhing
Pressure	0					(	Ø	1294
Flow Characteristics								
Puff	6/8	1	17 N		77 N		17(K)	CO2
Steady Flow	1709		77.8		77.8		₩ <u></u>	WTR
Surges	V/8	1	77.8		7 N		70	GAS
Down to nothing	A) Z	1	7.8		VIN		D N	If applicable type
Gas or Oil	V/(S)		112		Y / N	1		fluid injected for
Water	Y/(K)		1/2		1/8		76	Waterflood
Remarks: Picase state for e			Information r	regarding blee	d down or c	entinuous huild	up if applic	<b>34.</b>
Signature: Chin Fem						OIL CONSERVATION DIVISION		
Printed name						Entered into RBDMS		
Title:						-lest	· · · · · · · · · · · · · · · · · · ·	JOA
E-mail Address.	· · · · · · · · · · · · · · · · · · ·	,	7,	<del></del>				
Dute:	Phone.	<i>]</i>	// \			<del></del>	<del>in eme</del> ricans since er	purporente de la companya de la
	Witness &	mus 1	1.1.15		I			İ