

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 29 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP	API Number 30-025-02264
Property Name Vacuum Grayburg San Andres Unit	Well No. 039

2. Surface Location

PL - Lot H	Section 2	Township 18 S	Range 34 E	Feet from 1980	N/S Line N	Feet From 660	E/W Line E	County Lea
---------------	--------------	------------------	---------------	-------------------	---------------	------------------	---------------	---------------



Well Status

TAP'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER GAS	DATE 4/13/19
-------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	50	150
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness	