

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		API Number 30-025-8637
Property Name JALMAT FIELD YATES SAND UNIT		Well No. 147

1 Surface Location

UL - Lot A	Section 23	Township 22	Range 35	Feet from 660	N/S Line N	Feet from 660	E/W Line E	County Lea
----------------------	----------------------	-----------------------	--------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD NO	PRODUCER NO	GAS NO	DATE 8-20-19
-------------------------	----------------------	-----------------------	------------------	-----------------------	------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interval 1	(C) Interval 2	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	50	900
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD

AUG 23 2019

RECEIVED

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com		27	
Date:	Phone: 575-399-3329		
Witness: Kerry Fortner - OCD			

399-3321

INSTRUCTIONS ON BACK OF THIS FORM