

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name Breitburn		API Number 30-025-37492	
Property Name TALMAT Field YATES		Well No. 223	

1. Surface Location

UL - Lot 0	Section 11	Township 22S	Range 35E		Feet from 662	NS Line S	Feet from 1810	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--	-------------------------	---------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 8-21-19
------------------	-----------	----------------	-----------	------------	-----------------	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern#1	(C) Intern#2	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	000
Flow Characteristics					
Pull	Y	Y	Y	Y	CO2 —
Steady Flow	Y	Y	Y	Y	WTR —
Surges	Y	Y	Y	Y	GAS —
Down to nothing	Y	Y	Y	Y	Type of Flow Indicated by Waveform: appears
Gas or Oil	Y	Y	Y	Y	
Water	Y	Y	Y	Y	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

MIT

HOBBS OCD

AUG 23 2019

RECEIVED

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test OK	
E-mail Address:			
Date:	Phone:		
Witness: Don Holman			

19

INSTRUCTIONS ON BACK OF THIS FORM