

District I
 1625 N French Dr., Hobbs, NM 88240
 Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

AUG 02 2019

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name TLT SWD		API Number 30-025-31443	
Property Name Lost Tank SWD		Well No. 11	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
E	31	21S	32E	1980	N	1060	W	Lea

Well Status

TA'D WELL YES <input checked="" type="radio"/>	SHUT-IN YES <input checked="" type="radio"/>	INJ INJ	INJECTOR <input checked="" type="radio"/>	PRODUCER OIL	GAS	DATE 7-31-19
---	---	------------	--	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod.Csng	(E)Tubing
Pressure	0	N/A	N/A	0	400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input checked="" type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	


Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

MIT
Leak Troubleshooting
See # 87A15936
cal date: 6-25-19

Signature: Nathan Gibbs	OIL CONSERVATION DIVISION
Printed name: Nathan Gibbs	Entered into RBDMS
Title:	Re-test X
E-mail Address:	
Date: 7-31-19	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

PRINTED IN U.S.A.



DATE BR 2222
19-10-19

6-2-59
S/N 8-11-59
CALCULATED BY MRS. S. M. S.

RECEIVED
AUG 02 2019
HOBBS OGD

START →

MIN.

MIN.

MIN.

MIN.

MIN.