Submit 3 Copies To Appropriate District Office	co Form C-103
District I Wing 27, 20	
1625 N French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W Grand Ave. Artesia NM 88210 D = OIL CONSERVATION D	OIVISION 30-025-39130 5 Indicate Type of Lease
District III DEC 0 3 220 South St. Franci	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87419	STATE FEE 6. State Oil & Gas Lease No.
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 8741 District IV 1220 S. St. Francis Dr, Santa Fe, NM 18750 87505	6. State Off & Gas Lease No. V-07612
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	SUCH HIGHTOWER STATE UNIT
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 3
2. Name of Operator MURCHISON OIL & GAS, INC.	9. OGRID Number 015363
2. Name of operator More modernson on a day, inc.	9. OGRID Number 013303
3. Address of Operator 1100 MIRA VISTA BLVD. 10. Pool name or Wildcat	
PLANO, TX. 75093-4698	HIGHTOWER, PERMO PENN
4. Well Location	
Unit Letter 1 : 1750 feet from the SOUTH line and 330 feet from the EAST line	
Section 27 Township 12S Range 33E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐	
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☒	
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state all per	
of starting any proposed work). SEE RULE 1103. For Multiple	
or recompletion.	
Drilled a 12-1/4" hole to a depth of 3820' on 10/12/2008. Ran 9-5/8" casing as follows:	
1 Float Shoe 1'	
1 jt. 9-5/8" 40#/FT J-55 LT&C 45"	
1 Float Collar 2'	
87 jts. 9-5/8" 40#/FT J-55 LT&C <u>3776'</u> 3824'	
Set casing @ 3801'. Cement w/ 760 SXS. EconoCem + 10% BWOC Ber	ptonite + 8 PDS calt + 1 PDS Phano seal WT = 11 0 png Vield
= 2.47 cuft./sx (366 bbls), WR = 14.21 GPS. Tail w/ 200 SXS Halcem-C	
bbls), WR = 6.40 GPS. Bumped plug w/ 1500 PSI. Plug held OK. Circui	
install "B" section. Test to 2000 PSI. OK. Nipple up 11" 5M BOP. Te	st choke, manifold and BOP to 250 PSI low and 5000 PSI high
pressures. Test annular to 250 PSI low and 2500 PSI high pressures. I	
casing to 1500 PSI. Tested OK. Resume drilling 8-3/4" hole.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-	
grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.	
SIGNATURE () TITLE Vice President Operations DATE 12/2/2008	
SIGNATURE (Lunch all TITLE Vice President Operations DATE 12/2/2008	
Type or print name A. Arnold Nall E-mail address: arnall@jdmii.com Telephone No. (972) 931-0700	
Type or print name A. Arnold Nall E-mail address: arnall@jdmii.com Telephone No. (972) 931-0700 For State Use Only	
PETROLEIM ENGINEED	
APPROVED BY: TITLE TITLE DATE C n 4 2008	
Conditions of Approval (if any):	