

PIA'd. 10/14/2009
MRS. OK TO RELEASE

RECEIVED

Submit 2 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OCT 13 2009

HOBBSOCD

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 25, 2007

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-025-29451
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Reed AXV Com
8. Well Number	1
9. OGRID Number	255333
10. Pool name or Wildcat	Edison; Morrow, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: ☐ Oil Well ☒ Gas Well ☐ Other	
2. Name of Operator Lime Rock Resources A, L.P.	
3. Address of Operator Heritage Plaza, 1111 Bagby, Suite 4600, Houston, Texas 77002	
4. Well Location Unit Letter: <u>K</u> : <u>1,870</u> feet from the <u>South</u> line and <u>2,080</u> feet from the <u>West</u> line Section <u>12</u> Township <u>15S</u> Range <u>34E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4,063' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
OTHER: ☐		☒ Location is ready for OCD inspection after P&A	

- X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
X All other environmental concerns have been addressed as per OCD rules.
X Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.

SIGNATURE C. Tim Miller TITLE Vice President - Operations DATE 10-09-2009

TYPE OR PRINT NAME: C. Tim Miller E-MAIL: tmiller@limerockresources.com PHONE: (713) 292-9514
For State Use Only

APPROVED BY: Mary Jo Brown TITLE Compliance Officer DATE 10/14/2009
Conditions of Approval (if any):