

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY The Superior Oil Company, Midland, Texas
(Address)

LEASE W. C. Speed WELL NO. 2 UNIT N S 14 T -12-S R -32-E
DATE WORK PERFORMED -- POOL Caprock (Queen)

This is a Report of: (Check appropriate block) Results of Test of Casing Shut-off
 Beginning Drilling Operations Remedial Work
 Plugging Other Temporarily Abandoned

Detailed account of work done, nature and quantity of materials used and results obtained.

2-15-59:

Well is temporarily abandoned with consideration of possible secondary recovery application.

THE COMMISSION MUST BE NOTIFIED
EVERY 6 MONTHS ON FORM C-103
AS TO THE WELL STATUS AND YOUR
FUTURE PLANS FOR THIS WELL.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____

Witnessed by _____ (Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: John W. Runyan
Title _____
Date _____

Name Robert B. Wilson (Robert B. Wilson)
Position Production Engineer
Company The Superior Oil Company