

U.S. G. C.
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM 010 8997 (A)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
J.F. FARRELL-USA

9. WELL NO.
12

10. FIELD AND POOL, OR WILDCAT
CHAUEROO-SAN ANDRES

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
28-7-33 NMPM

12. COUNTY OR PARISH
ROOSEVELT

13. STATE
N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Co spreaded 11" hole at 9:PM 1/26/66.
On 1/27/66, 8 5/8" OD 24# J-55 Casing was set at 412' w/ 250 sq. Cement Cive. After 740C 18 hours tested casing w/ 1500 psi for 30 minutes. Test O.K.
Reduced hole to 7 7/8" at 412' and resumed drilling operations.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Area Supr DATE 1-28-66

(This space for Federal or State office use)

044-USGS-14
APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:
1- JWB
1- SUSP
1- RRY
2- Champlin Pites Co.
1- Warren Amer Oil Co
1- Kern Co Rand Co
3- Tom Brown Drily Co

APPROVED

FEB 1 1966

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER