

(SUBMIT IN TRIPLICATE)

Land Office Lea County

Lease No. 058699 A

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 24, 1948

Well No. Miller 3 is located 660 ft. from N line and 1980 ft. from E line of sec. 26

SE 1/4 Sec. 26 17 S 32E R11PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Maljamar Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In accordance with our report of 3-11-48 we plugged and abandoned the above well, we recovered 586 ft. of the 5 1/2" casing. The well was circulated with heavy mud, using about eight tons. A cement plug of ten sacks was put in the bottom, a plug of fifteen sacks of cement was spotted at 586 feet and a plug of ten sacks was put in the top of the hole with four inch regulation marker set in same. Location was cleaned up.

TD 4358- PB 4196

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ross Seare, et al

Address Artesia, New Mexico

By Ross Seary

Title Agent