

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-1481

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Don H. Wilson | 8. Farm or Lease Name State "AT" |
| 3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N M 88240 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 4 TOWNSHIP 19S RANGE 37E NMPM. | 10. Field and Pool, or Wildcat Bumont Oil |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3706 DF | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| | |
|--|--|
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |
| OTHER <input type="checkbox"/> | OTHER <input type="checkbox"/> |
| PLUG AND ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/19/77 Ran tubing to 2190 and spotted 35 sacks cement, top of plug @ 2087. Pulled 11 joints tubing & spotted 30 sacks cement @ 1750. Pulled 47 joints tubing & spotted 35 sacks cement @ 379'.

5/20/77 Tagged top of plug @ 280'. Set 10 sack plug at surface, erected marker.

Plugging operations witnessed by N. E. Clegg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Herbert Helms TITLE Agent DATE 5/27/77

APPROVED BY Edwin W. Long TITLE DIVISION & GAS DIRECTOR

CONDITIONS OF APPROVAL, IF ANY: