

**NEW MEXICO OIL CONSERVATION COMMISSION**  
**MISCELLANEOUS REPORTS ON WELLS**

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS	<input type="checkbox"/>	REPORT ON REPAIRING WELL	<input type="checkbox"/>
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	<input type="checkbox"/>	REPORT ON PULLING OR OTHERWISE ALTERING CASING	<input type="checkbox"/>
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON DEEPENING WELL	<input type="checkbox"/>
REPORT ON RESULT OF PLUGGING OF WELL	<input type="checkbox"/>		<input type="checkbox"/>

March 5, 1952

Monument, New Mexico

Date

Place

Following is a report on the work done and the results obtained under the heading noted above at the.....

**Amerada Petroleum Corporation** Fred Turner Jr. "A" Well No. **5** in the  
 Company or Operator Lease  
**SW/4, NE/4** of Sec. **18** T. **20-S** R. **38-E**, N. M. P. M.,  
**Skaggs** Pool **Laa** County.

March 5, 1952

The dates of this work were as follows:.....

Notice of intention to do the work was ~~XXXX~~ submitted on Form C-102 on **March 4, 1952**, 19.....  
 and approval of the proposed plan was ~~XXXX~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

**3710'- Total Depth - Line. Ran Temperature Survey - top of cement outside 5 1/2" casing at 1184'. Ratio of actual to calculated fill, 35.6%. Picked up 2-7/8" Drill Pipe w/4-3/4" Bit and checked top of cement at 3643' and tested 5 1/2" casing with 800# for 1/2 hour - no pressure drop. Drilled cement from 3643' to 3710' and checked casing w/800# for 1/2 hour - no pressure drop. Continued with completion operations. Will drill 4-3/4" hole from 3710' to approximately 3915' and complete from open hole.**

Witnessed by **E. E. Shirley** **Amerada Petroleum Corporation** **Farm Boss -**  
 Name Company Title

APPROVED:  
 OIL CONSERVATION COMMISSION

*Ray Yakhrough*  
 Name  
 Title  
 Date 19.....

I hereby swear or affirm that the information given above is true and correct.

Name *Ray Yakhrough*  
 Position **Assistant District Superintendent**  
 Representing **Amerada Petroleum Corporation**  
 Company or Operator  
 Address **Drawer D, Monument, New Mexico**