



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office New Mexico  
Lease No. 0888  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<b>Subsequent Report of Drill Stem Test X</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 17, 1960

**Federal-Low**  
Well No. 1 is located 1980 ft. from XX line and 660 ft. from XX line of sec. 7  
SW 1/4 - Sec. 7 26-E 38-E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat Lee New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3031 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

May 15, 1960- DST #3, Interval 9876-9980', no water cushion, tool open 55 min., gas to surface in 5 min., rate 931 MCFD decreased to 600 MCFD, oil to surface in 35 min. Heavy oil & gas spray to pit 15 min. No estimate of quantity of oil, reversed gas & oil from drill pipe. Recovered 90' clean oil below sub. No water. IFBHP 525#, FFBHP 1310#, 30 min. closed in pressure 4210#.

May 16, 1960- DST #4, Interval 9876-10,005', 1000' water cushion. Tool open 2 hr. 44 min. Gas to surface in 14 min. Water cushion to surface 1 hr. 8 min. Oil to surface 1 hr. 33 min. Cleaned to pit through 1" choke 11 min. Flowed to tank 1 hr. 25.7 bbl/oil, 1/2" choke surface flowed surface press. 390-360#, gravity 40.6 @ 60° F, GOR 1530/1. No water. Reversed oil & gas from drill pipe. Recovered 90' pipe line oil under sub. No water. IFBHP 685#, FFBHP 1810#, 30 min. closed in pressure 4110#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Forest Oil Corporation, Agent for Forest-Bryson Corporation  
Address Box 4106  
Odessa, Texas  
By J. K. Wright  
Title Division Production Sup't.