Page 1 of 2

Javelina Unit P429 (429H, 430H, 431H, 432H) Facility ID fVV2214455406 (Weekly Inspection log)											
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES			
8/7/2024	good	yes	ok	no	no	no	yes	no issue to report			
8/14/2024	good	yes	ok	no	no	no	yes	no issue to report			
8/21/2024	good	yes	ok	no	no	no	yes	no issue to report			
8/28/2024	good	yes	ok	no	no	no	yes	no issue to report			
9/4/2024	good	yes	ok	no	no	no	yes	no issue to report			
9/11/2024	good	yes	ok	no	no	no	yes	no issue to report			
9/18/2024	good	yes	ok	no	no	no	yes	no issue to report			
9/25/2024	good	yes	ok	no	no	no	yes	no issue to report			
10/2/2024	good	yes	ok	no	no	no	yes	no issue to report			
10/9/2024	good	yes	ok	no	no	no	yes	no issue to report			
10/16/2024	good	yes	ok	no	no	no	yes	no issue to report			
10/23/2024	good	yes	ok	no	no	no	yes	no issue to report			
10/30/2024	good	yes	ok	no	no	no	yes	no issue to report			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 399933

CONDITIONS

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	399933
	Action Type:
	[C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	11/13/2024