

SD 15 22 FED COM P404 - Facility ID fJMB2232539215 (Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
5/19/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/20/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/21/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/22/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/23/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/24/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/25/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/26/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/27/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/28/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/29/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/30/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
5/31/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/1/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/2/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/3/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/4/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/5/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/6/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/7/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/8/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/9/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/10/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/11/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/12/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/13/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/14/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/15/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/16/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/17/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/18/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/19/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/20/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/21/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/22/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/23/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/24/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/25/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/26/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/27/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/28/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/29/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
6/30/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/1/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/2/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/3/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/4/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/5/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/6/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/7/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/8/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/9/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/10/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/11/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/12/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/13/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection
7/14/2025	Good	4'	Good	none	none	none	good	DSR Daily visual inspection

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 492583

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 492583
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	8/7/2025