

Cotton Draw Panther 3 34 FED & 10 15 FED COM (Pad 604) (604H, 605H, 606H, 615H, 613H, 614H) [fJWH2436631971] (Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
8/9/2025	Good	>3.0'	Good	None	None	None	Good	Checked during initial mobilization to pad
8/10/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/11/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/12/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/13/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/14/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/15/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/16/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/17/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/18/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/19/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/20/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/21/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/22/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/23/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/24/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/25/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/26/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/27/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/28/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/29/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/30/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
8/31/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/1/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/2/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/3/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/4/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/5/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/6/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/7/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/8/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/9/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/10/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/11/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/12/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/13/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/14/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/15/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/16/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/17/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/18/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/19/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/20/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/21/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/22/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/23/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/24/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/25/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/26/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/27/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/28/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/29/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
9/30/2025	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 513220

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 513220
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	10/8/2025