

State of New Mexico
 Energy Minerals and Natural Resources
 Department Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505
<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

Recycling Facility and/or Recycling Containment

Type of Facility: Recycling Facility Recycling Containment*
Type of action: Permit Registration
 Modification Extension (01/11/2026-01/11/2027)
 Closure Other (explain) _____

*** At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: EOG Resources Inc. (For multiple operators attach page with information) OGRID #: 7377
 Address: 5509 Champions Dr. Midland, Texas 79706

Facility or well name (include API# if associated with a well): Chili Pepper Water Recycling Facility and Containment Pit

OCD Permit Number: 1RF-26 (For new facilities the permit number will be assigned by the district office)

U/L or Qtr/Qtr NENW (C) Section 17 Township 23S Range 35E County: Lea

Surface Owner: Federal State Private Tribal Trust or Indian Allotment

2.

Recycling Facility:

Location of recycling facility (if applicable): Latitude 32.3099405 Longitude -103.3922060 NAD83

Proposed Use: Drilling* Completion* Production* Plugging *

***The re-use of produced water may NOT be used until fresh water zones are cased and cemented**

Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.

Fluid Storage

Above ground tanks Recycling containment Activity permitted under 19.15.17 NMAC explain type _____
 Activity permitted under 19.15.36 NMAC explain type: _____ Other explain _____
 For multiple or additional recycling containments, attach design and location information of each containment

Closure Report (required within 60 days of closure completion): Recycling Facility Closure Completion Date: _____

3.

Recycling Containment:

Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year) 01/11/2026-01/11/2027

Center of Recycling Containment (if applicable): Latitude 32.3099372 Longitude -103.3939422 NAD83

For multiple or additional recycling containments, attach design and location information of each containment

Lined Liner type: Thickness 60 mil LLDPE HDPE PVC Other _____

String-Reinforced

Liner Seams: Welded Factory Other _____ Volume: 1MM bbl Dimensions: L 600 x W 600 x D 16(inside)

Recycling Containment Closure Completion Date: _____

4.

Bonding:

Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)

Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$_____ (work on these facilities cannot commence until bonding amounts are approved)

Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify _____

6.

Signs:

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

Yes No
 NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Yes No
 NA

Within the area overlying a subsurface mine.

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Yes No

Within an unstable area.

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Yes No

Within a 100-year floodplain. FEMA map

Yes No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

- Topographic map; visual inspection (certification) of the proposed site

Yes No

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Yes No

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Yes No

Within 500 feet of a wetland.

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

Yes No

9.

Recycling Facility and/or Containment Checklist:*Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.*

- Design Plan - based upon the appropriate requirements.
- Operating and Maintenance Plan - based upon the appropriate requirements.
- Closure Plan - based upon the appropriate requirements.
- Site Specific Groundwater Data -
- Siting Criteria Compliance Demonstrations -
- Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Morgan Hrcirik Title: Sr. Regulatory Administrator

Signature: Morgan Hrcirik Date: 01/07/2026

e-mail address: morgan_hrcirik@eogresources.com Telephone: (832) 627-5450

11.

OCD Representative Signature: Victoria Venegas Approval Date: 02/02/2026

Title: Senior Environmental Scientist OCD Permit Number: 1RF-26

OCD Conditions

Additional OCD Conditions on Attachment



P.O. Box 2267, Midland, Texas 79702
Phone: (832) 627-5450

January 7, 2026

Ms. Victoria Venegas, Environmental Specialist
EMNRD- Oil Conservation Division
506 W. Texas Artesia, NM 88210

Re: EOG Chili Pepper Pit 1RF-26

Dear Ms. Venegas:

Thank you for allowing EOG to continue to promote water reuse in the State of New Mexico for our operations. EOG (Owner/Operator), and Accelerated (operator) plan to have active completion operations near this pit location into 2026. EOG Resources Inc., would like to formally request an extension to our currently approved permit from 1/11/2026 - 1/11/2027.

Sincerely,

Morgan Hrcicirk

Morgan Hrcicirk
Sr. Regulatory Administrator

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Monday, February 2, 2026 2:04 PM
To: Morgan_HRNCIRIK@eogresources.com
Subject: 1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT
[FOY1805031625]
Attachments: C-147 1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT
[FOY1805031625] 02.02.2026.pdf

1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT [FOY1805031625]

Good afternoon Ms. Hrncirik,

NMOCD has reviewed the registration/permit annual extension request for 1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT [FOY1805031625], received from EOG RESOURCES INC [7377] on 01/16/2026, Action ID **543386**. The registration/permit extension request is approved with the following conditions of approval:

- 1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT [FOY1805031625] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 16, 2026. The new registration/permit expiration date is January 16, 2027.
- EOG RESOURCES INC [7377] will continue to operate, maintain, and close the 1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT [FOY1805031625] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via OCD Permitting.
- EOG RESOURCES INC [7377] will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. EOG RESOURCES INC [7377] may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically to OCD Permitting. A request to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 long form through OCD Permitting. OCD will grant an additional 6 months to operate the containment if all the requirements of 19.15.34 are met. However, if after that 6-month period the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements per 19.15.34.14.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT [FOY1805031625] is limited to wells owned or operated by EOG RESOURCES INC [7377].
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- EOG RESOURCES INC [7377] will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field wastes at 1RF-26 - Chili Pepper Water Recycling Facility and Containment [FOY1805031625].
- EOG RESOURCES INC [7377] will comply with all other OCD rules.
- EOG RESOURCES INC [7377] must perform weekly inspections of the containment and leak detection system.
- If EOG RESOURCES INC [7377] wishes to extend the registration/permit past January 16, 2027, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a

case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year. Additional requests must be submitted to OCD through the OCD Permitting on a Form C-147 as an extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than December 16, 2026.

Please let me know if you have any additional questions.

Regards,

Victoria Venegas • Senior Environmental Scientist
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
575.909.0269 | Victoria.Venegas@emnrd.nm.gov



Forms Report

Forms Summary

Total Forms: 58

Form Date	Status	Form ID	Form Type	Application Name
01/13/2026	Completed	13433455	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432963	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432960	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432958	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432957	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432956	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432955	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432954	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432953	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432946	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432944	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432940	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432939	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432937	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432932	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432902	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432901	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432900	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432897	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432855	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432854	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432852	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13432851	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13429507	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13429506	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13427583	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13427582	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13427581	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13427578	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13427577	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	13420836	Reuse Pit Inspection - NM	iEnvironmental
01/13/2026	Completed	12747374	Reuse Pit Inspection - NM	iEnvironmental
01/10/2026	Completed	13421021	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13432903	Reuse Pit Inspection - NM	iEnvironmental
01/01/2026	Completed	13432823	Reuse Pit Inspection - NM	iEnvironmental
12/26/2025	Completed	13432821	Reuse Pit Inspection - NM	iEnvironmental
09/01/2025	Completed	12800951	Reuse Pit Inspection - NM	iEnvironmental
06/30/2025	Completed	13429505	Reuse Pit Inspection - NM	iEnvironmental
06/23/2025	Completed	12664008	Reuse Pit Inspection - NM	iEnvironmental
06/09/2025	Completed	13427579	Reuse Pit Inspection - NM	iEnvironmental
05/26/2025	Completed	12425058	Reuse Pit Inspection - NM	iEnvironmental
05/19/2025	Completed	13432930	Reuse Pit Inspection - NM	iEnvironmental
05/12/2025	Completed	13432929	Reuse Pit Inspection - NM	iEnvironmental
05/05/2025	Completed	13432928	Reuse Pit Inspection - NM	iEnvironmental
04/28/2025	Completed	13432927	Reuse Pit Inspection - NM	iEnvironmental
04/21/2025	Completed	13432926	Reuse Pit Inspection - NM	iEnvironmental
04/14/2025	Completed	13432912	Reuse Pit Inspection - NM	iEnvironmental
04/07/2025	Completed	13432899	Reuse Pit Inspection - NM	iEnvironmental
03/31/2025	Completed	13433469	Reuse Pit Inspection - NM	iEnvironmental



Form Date	Status	Form ID	Form Type	Application Name
03/24/2025	Completed	13433449	Reuse Pit Inspection - NM	iEnvironmental
03/10/2025	Completed	12360617	Reuse Pit Inspection - NM	iEnvironmental
03/03/2025	Completed	13433448	Reuse Pit Inspection - NM	iEnvironmental
02/17/2025	Completed	12281781	Reuse Pit Inspection - NM	iEnvironmental
02/10/2025	Completed	13432850	Reuse Pit Inspection - NM	iEnvironmental
02/03/2025	Completed	13427576	Reuse Pit Inspection - NM	iEnvironmental
01/27/2025	Completed	13429512	Reuse Pit Inspection - NM	iEnvironmental
01/20/2025	Completed	12211542	Reuse Pit Inspection - NM	iEnvironmental
01/13/2025	Completed	13433444	Reuse Pit Inspection - NM	iEnvironmental



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13433455

Scheduled

06/09/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432933

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432963

Scheduled

12/06/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432960

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432960

Scheduled

11/29/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13432959

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432958

Scheduled

11/15/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432957

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432957

Scheduled11/08/2025 **Completed**

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432956

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432956

Scheduled

11/01/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13432955

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432955

Scheduled

10/25/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13432954

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432954

Scheduled

10/18/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432953

Comments

General

Visual inspection conducted:	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432953

Scheduled

10/11/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13432946

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432946

Scheduled

10/04/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13432902

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432944

Scheduled

09/13/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432941

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432940

Scheduled

08/30/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432939

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432939

Scheduled

08/23/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432937

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432937

Scheduled

08/16/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432901

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432932

Scheduled

05/31/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432930

Comments**General**

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:
671

Schedule Name:
Weekly

Schedule Counter:
1

Schedule Period:
WEEK

Program Type:
Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432902

Scheduled

09/27/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13427582

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432901

Scheduled

08/09/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13432855

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432900

Scheduled

06/28/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432853

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432897

Scheduled

02/22/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jorge Gutierrez Team

Assigned Member**Associated Form**

13432850

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432855

Scheduled

08/02/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13427581

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432854

Scheduled

07/19/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13427580

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432852

Scheduled

04/05/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13427578

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432851

Scheduled

03/15/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Assigned Member**Associated Form**

13427577

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13429507

Scheduled

09/08/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

12800951

Comments

Auto-Deferred by System due to missed inspection.

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13429506

Scheduled

07/14/2025

Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

12747374

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13427583

Scheduled

12/18/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13429508

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13427582

Scheduled

09/20/2025 01/13/2026

Completed**Status**

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13429507

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13427581

Scheduled

07/26/2025 01/13/2026

Completed**Status**

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Associated Form**

13429506

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13427578

Scheduled

03/29/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13429510

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13427577

Scheduled03/08/2025 **Completed**

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Assigned Member**Associated Form**

13429511

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13420836

Scheduled

12/13/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13281235

Comments

Auto-Deferred by System due to missed inspection.

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

12747374

Scheduled

07/07/2025 Completed

01/13/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Team

Assigned Member**Previous Form**

12664008

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13421021

Scheduled

01/12/2026 Completed

01/10/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jorge Gutierrez Team

Associated Form

13420836

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432903

Scheduled

01/08/2026 Completed

01/08/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Alan Ramirez Team

Assigned Member**Associated Form**

13432823

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432823

Scheduled

01/01/2026 Completed

01/01/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432821

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432821

Scheduled

12/25/2025 Completed

12/26/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Associated Form

13427583

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

12800951

Scheduled

09/01/2025 Completed

09/01/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ricardo Villegas Team

Previous Form

12747374

Comments

General

Visual inspection conducted:	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13429505

Scheduled

06/30/2025 Completed

06/30/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

12664008

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

12664008

Scheduled

06/23/2025 Completed

06/23/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Team

Assigned Member**Previous Form**

12425058

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13427579

Scheduled

06/14/2025 Completed

06/09/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Associated Form

13429438

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

12425058

Scheduled

05/26/2025 Completed

05/26/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Assigned Member**Previous Form**

12360617

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432930

Scheduled05/24/2025 **Completed**

05/19/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432929

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432929

Scheduled

05/17/2025 Completed

05/12/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432928

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432928

Scheduled

05/10/2025 Completed

05/05/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Associated Form

13432927

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432927

Scheduled

05/03/2025 Completed

04/28/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Associated Form

13432926

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432926

Scheduled

04/26/2025 Completed

04/21/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432912

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432912

Scheduled04/19/2025 **Completed**

04/14/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432899

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432899

Scheduled

04/12/2025 Completed

04/07/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13432852

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13433469

ScheduledCompleted
03/31/2025

Completed

03/31/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13433449

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13433449

Scheduled

03/24/2025 Completed

03/24/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13433436

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

12360617

Scheduled

03/10/2025 Completed

03/10/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Previous Form

12281781

Comments

General

Visual inspection conducted:	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13433448

Scheduled

03/03/2025 Completed

03/03/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Associated Form

13433428

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

12281781

Scheduled

02/17/2025 Completed

02/17/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Previous Form

12211542

Comments

General

Visual inspection conducted:	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13432850

ScheduledCompleted
02/15/2025

02/10/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13427576

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13427576

Scheduled

02/08/2025 Completed

02/03/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13429512

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13429512

Scheduled

01/27/2025 Completed

01/27/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

12211542

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

12211542

Scheduled

01/20/2025 Completed

01/20/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jorge Gutierrez Team

Previous Form

11895160

Comments

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33831

Site Name: OC CHILI PEPPER REUSE PIT

Reuse Pit Inspection - NM

Property

OC CHILI PEPPER REUSE PIT

Property ID

074828000

Form Description

Reuse Pit Inspection - NM

Form ID

13433444

ScheduledCompleted
01/13/2025

Completed

01/13/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Ryan Eldridge Team

Assigned Member**Associated Form**

13429513

Comments**General**

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 543386

CONDITIONS

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 543386
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	• 1RF-26 - CHILI PEPPER WATER RECYCLING FACILITY AND CONTAINMENT [FOY1805031625] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 16, 2026. The new registration/permit expiration date is January 16, 2027. • If EOG RESOURCES INC [7377] wishes to extend the registration/permit past January 16, 2027, a registration/permit extension request must be submitted to OCD no later than December 16, 2026.	2/2/2026