District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

**State of New Mexico
Energy Minerals and Natural
Resources Department**

**Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505**

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2102237559
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	XTO Energy	OGRID	5380
Contact Name	Kyle Littrell	Contact Telephone	432-221-7331
Contact email	kyle.littrell@exxonmobil.com	Incident # *(assigned by OCD)*	
Contact mailing address	522 W. Mermod, Carlsbad, NM 88220		

Location of Release Source

Latitude 32.15458   Longitude -104.01577

(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Goldenchild	Site Type	CTB
Date Release Discovered	1/15/2021	API# *(if applicable)*	

Unit Letter	Section	Township	Range	County
P	5	25S	29E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (*Name:* _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☐ Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	☐ Yes ☐ No
☒ Condensate	Volume Released (bbls) 0.11	Volume Recovered (bbls) 0
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release LO arrived on location and found fluid burping out the LP flare. The VRT pressured up and pushed trapped fluid out the flare which ignited and extinguished itself when it impacted the ground. A third-party contractor has been retained for remediation activities.

Form C-141

Page 2

State of New Mexico
Oil Conservation Division

Incident ID	NAPP2102237559
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☒ Yes ☐ No	If YES, for what reason(s) does the responsible party consider this a major release? Fire at facility

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Yes, by Adrian Baker to 'Bratcher, Mike, EMNRD'; Venegas, Victoria, EMNRD; Hamlet, Robert, EMNRD; emily.hernandez@state.nm.us; 'Mann, Ryan' on Friday, January 15, 2021 1:42 PM via email.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

☒ The source of the release has been stopped.

☒ The impacted area has been secured to protect human health and the environment.

☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have <u>not</u> been undertaken, explain why:

NA

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Kyle Littrell   Title: Environmental Manager

Signature: Date: 1-22-21

email: kyle.littrell@exxonmobil.com   Telephone: 432-221-7331

OCD Only

Received by: Ramona Marcus   Date: 5/3/2021

Location:	Goldenchild CTB	
Spill Date:	**1/15/2021**	
Area 1		
Approximate Area =	472.00	sq. ft.
Average Saturation (or depth) of spill =	0.50	inches
Average Porosity Factor =	0.03	
VOLUME OF LEAK		
Total Condensate=	0.11	bbls
TOTAL VOLUME OF LEAK		
Total Condensate=	**0.11**	**bbls**
TOTAL VOLUME RECOVERED		
Total Condensate=	**0.00**	**bbls**

CONDITIONS

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Action   23687

CONDITIONS OF APPROVAL

Operator:	OGRID:	Action Number:	Action Type:
XTO ENERGY, INC 6401 Holiday Hill Road Building #5 Midland, TX79707	5380	23687	C-141

OCD Reviewer	Condition
rmarcus	None