

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2106357887
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party XTO Energy	OGRID 5380
Contact Name Kyle Littrell	Contact Telephone 432-221-7331
Contact email kyle.littrell@exxonmobil.com	Incident # (assigned by OCD)
Contact mailing address 522 W. Mermod, Carlsbad, NM 88220	

Location of Release Source

Latitude 32.09421 Longitude -103.83555
(NAD 83 in decimal degrees to 5 decimal places)

Site Name PLU PB 25-25-30	Site Type Battery
Date Release Discovered 2/22/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
N	25	25S	30E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 95	Volume Recovered (bbls) 95
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Corrosion on a water dump line caused fluid to release into impermeable containment. All fluids were recovered. A 48-hour liner inspection was sent to NMOCD District 2. Liner was inspected and determined not to be operating as designed. A third-party contractor has been retained for remediation activities.

Form C-141


State of New Mexico
Oil Conservation Division

Page 2

Incident ID	NAPP2106357887
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? A release equal to or greater than 25 barrels.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? By Adrian Baker to 'Bratcher, Mike, EMNRD'; Venegas, Victoria, EMNRD; 'robert.Hamlet@state.nm.us' emily.hernandez@state.nm.us on Tuesday, February 23, 2021 8:46 AM via email.	

Initial Response*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped.	
<input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: NA	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Adrian Baker</u>	Title: <u>Environmental Coordinator</u>
Signature: <u></u>	Date: <u>3/4/21</u>
email: <u>adrian.baker@exxonmobil.com</u>	Telephone: <u>432-221-7331</u>
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>5/4/2021</u>

NAPP2106357887

Location:	PLU PB 25-25-30	
Spill Date:	2/22/2021	
Area 1		
Approximate Area =	533.39	cu.ft.
VOLUME OF LEAK		
Total Produced Water =	95.00	bbls
TOTAL VOLUME OF LEAK		
Total Produced Water =	95.00	bbls
TOTAL VOLUME RECOVERED		
Total Produced Water =	95.00	bbls

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 23728

CONDITIONS OF APPROVAL

Operator:	OGRID:	Action Number:	Action Type:
XTO ENERGY, INC 6401 Holiday Hill Road Building #5 Midland, TX79707	5380	23728	C-141

OCD Reviewer	Condition
rmarcus	None