

MANLEY GAS TESTING, INC.

P.O. DRAWER 193
OFFICE(432)367-3024

FAX(432)367-1166

ODESSA, TEXAS 79760
E-MAIL: MANLEYGAST@AOL.COM

CHARGE..... 150 - 0
REC. NO. 3
TEST NUMBER.. 51172

DATE SAMPLED..... 02-19-21
DATE RUN..... 02-23-21
EFFECT. DATE..... 03-01-21

STATION NO. ... 633045

PRODUCER DURANGO MIDSTREAM

SAMPLE NAME.... ABO TOTAL FLARE GAS METER

TYPE: SPOT

RECEIVED FROM.. FRONTIER FIELD SERVICES LLC - MALJAMAR

FLOWING PRESSURE 22.7 PSIA

FLOWING TEMPERATURE 61 F

SAMPLED BY: FT

CYLINDER NO. ...

FRACTIONAL ANALYSIS CALCULATED @ 14.650 PSIA AND 60F

	MOL%	GPM (REAL)
HYDROGEN SULFIDE...	0.900	
NITROGEN.....	1.592	
CARBON DIOXIDE.....	1.001	
METHANE.....	71.994	
ETHANE.....	13.162	3.515
PROPANE.....	6.297	1.732
ISO-BUTANE.....	0.850	0.278
NOR-BUTANE.....	2.019	0.636
ISO-PENTANE.....	0.539	0.197
NOR-PENTANE.....	0.568	0.206
HEXANES +.....	1.078	0.470
TOTALS	100.000	7.034

H2S PPMV = 9000

'Z' FACTOR (DRY) = 0.9957
'Z' FACTOR (WET) = 0.9953

CALC. MOL. WT. = 22.94

..CALCULATED SPECIFIC GRAVITIES..

REAL, DRY 0.7954

REAL, WET 0.7927

..CALCULATED GROSS HEATING VALUES..

BTU/CF - REAL, DRY 1314

BTU/CF - REAL, WET 1291

DISTRIBUTION AND REMARKS:

N

ANALYZED BY: JT
** R **

APPROVED:





Facility: Empire Abo Gas Plant
Date: 6/19/2021

Flares D-2301 & D-2302		
Time	Event Type	Flare Volume (Mcf)
0:00	-	0.0
1:00	-	0.0
2:00	-	0.0
3:00	-	0.0
4:00	-	0.0
5:00	-	0.0
6:00	-	0.0
7:00	-	0.0
8:00	-	0.0
9:00	-	0.0
10:00	-	0.0
11:00	-	0.0
12:00	-	0.0
13:00	-	0.0
14:00	-	0.0
15:00	-	0.0
16:00	Malfunction	113.6
17:00	-	0.0
18:00	-	0.0
19:00	-	0.0
20:00	-	0.0
21:00	-	0.0
22:00	-	0.0
23:00	-	0.0

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 33057

QUESTIONS

Operator: FRONTIER FIELD SERVICES, LLC 10077 Grogans Mill Rd. The Woodlands, TX 77380	OGRID: 221115
	Action Number: 33057
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting or flaring caused by an emergency or malfunction	Yes
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a notification of a major venting or flaring	Yes, minor venting or flaring of natural gas.
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19.13.29.7 NMAC	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

Unregistered Facility Site

Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (##) yet.

Facility or Site Name	Not answered.
Facility Type	Not answered.

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	72
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	1
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting or flaring was discovered or commenced	06/19/2021
Time venting or flaring was discovered or commenced	04:00 PM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	06/19/2021
Time venting or flaring was terminated	07:00 PM
Total duration of venting or flaring in hours, if venting or flaring has terminated	1
Longest duration of cumulative hours within any 24-hour period during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure Gas Compressor Station Natural Gas Flared Spilled: 114 Mcf Recovered: 0 Mcf Lost: 114 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	Flare valve came open slightly due to low instrument air (Fail Open Valve). Switched rental air compressor when other one overheated. Operator could not foresee this event.
Steps taken to limit the duration and magnitude of venting or flaring	Switched air compressor quickly to close flare.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Began using rental unit until frozen unit is repaired/replaced.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 33057

CONDITIONS

Operator: FRONTIER FIELD SERVICES, LLC 10077 Grogans Mill Rd. The Woodlands, TX 77380	OGRID: 221115
	Action Number: 33057
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	6/22/2021