

Analysis Certificate Report

Lucid Energy Group-PURCHASER

6/10/2021 3:44 PM

3100 McKinnon St #800
Dallas, TX 75201

BROCK A BOWMAN

Analysis ID: 14750 **Alternate ID:** **Use Contract Values:** No

Name BLACK MARLIN CTB **Company Name:** Lucid Energy Group

Effective Date:	02/01/2021 08:00	Saturated HV:	1296.4	Sample Date:	02/04/2021
Valid Thru Date:	12/31/2078 00:00	As Del. HV:	1312.4	Sample ID:	6030-21020080-015A
Fixed Edit Date:	01/01/1900 00:00	Dry HV:	1317.8	Sample Type:	Spot
Last Update:	02/10/2021 15:18	Measured HV:	1317.8	Sample Pressure Base:	14.730
Data Acquisition:	File Transfer from Lab	WOBBE:	1481.1	Sample Temperature:	76.0
Data Source:	Lab Analysis	Water Content:	0.4	Sample Pressure:	106.7
Real Relative Density:	0.7917	Status:	Active	Lab Code:	

<u>Component</u>	<u>% Mol</u>	<u>GPM</u>	
Methane	73.7263		Dry Gravity
Ethane	10.9170	2.9315	Saturated Gravity
Propane	6.3423	1.7544	
I Butane	1.0171	0.3342	
N Butane	2.2476	0.7115	
I Pentane	0.7121	0.2615	
N Pentane	0.6187	0.2252	
Hexanes +	0.9048	0.3964	

Nitrogen	1.2382
CO2	1.8349
Oxygen	0.0000
H2O	0.4400
CO	0.0000
H2S	0.0010
Hydrogen	0.0000
Helium	0.0000
Argon	0.0000

Total	100.0000	6.6147
--------------	----------	--------

Sample Comments:

Configuration Comments:

Flaring Summary

battery	7/18/2021
Black Marlin Federal Com Tank Battery	1,186.50
Grand total	1,186.50

date

Data table:
flare_report_data (2)

Colors:

All values

battery

Sum(TOTAL FLARE (HP + LP))

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 36992

QUESTIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043 Action Number: 36992 Action Type: [C-129] Venting and/or Flaring (C-129)
--	---

QUESTIONS**Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting or flaring caused by an emergency or malfunction	No
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a notification of a major venting or flaring	Yes, major venting or flaring of natural gas.
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19.13.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

Unregistered Facility Site

Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (##) yet.

Facility or Site Name	Black Marlin CTB
Facility Type	Tank Battery - (TB)

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	74
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	2
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting or flaring was discovered or commenced	07/17/2021
Time venting or flaring was discovered or commenced	06:00 AM
Is the venting or flaring event complete	No
Date venting or flaring was terminated	Not answered.
Time venting or flaring was terminated	Not answered.
Total duration of venting or flaring in hours, if venting or flaring has terminated	Not answered.
Longest duration of cumulative hours within any 24-hour period during this event	10

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Normal Operations Producing Well Natural Gas Flared Spilled: 1,187 Mcf Recovered: 0 Mcf Lost: 1,187 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	False
Please explain reason for why this event was beyond your operator's control	Not answered.
Steps taken to limit the duration and magnitude of venting or flaring	Tap Rock is currently pending an ACO for this location. Per the NMOCDC email, we are allowed to flare this well until a decision is made on the ACO. Once a decision is made, Tap Rock will adjust accordingly.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Tap Rock is currently pending an ACO for this location. Per the NMOCDC email, we are allowed to flare this well until a decision is made on the ACO. Once a decision is made, Tap Rock will adjust accordingly.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 36992

CONDITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 36992
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	7/19/2021