

Analysis Certificate Report

Lucid Energy Group-PURCHASER

6/10/2021 3:44 PM

3100 McKinnon St #800
Dallas, TX 75201

BROCK A BOWMAN

Analysis ID: 14743		Alternate ID:		Use Contract Values: No	
Name	Gipple CDP	Company Name: Lucid Energy Group			
Effective Date:	10/01/2020 08:00	Saturated HV:	1317.8	Sample Date:	10/07/2020
Valid Thru Date:	12/31/2078 00:00	As Del. HV:	1331.4	Sample ID:	6030-20100094-006A
Fixed Edit Date:	01/01/1900 00:00	Dry HV:	1339.7	Sample Type:	Spot
Last Update:	10/23/2020 14:56	Measured HV:	1339.7	Sample Pressure Base:	14.730
Data Acqusition:	File Transfer from Lab	WOBBE:	1506.0	Sample Temperature:	103.0
Data Source:	Lab Analysis	Water Content:	0.7	Sample Pressure:	165.0
Real Relative Density:	0.7913	Status:	Active	Lab Code:	

<u>Component</u>	<u>% Mol</u>	<u>GPM</u>	Dry Gravity
Methane	71.9231		Saturated Gravity
Ethane	12.9015	3.4648	
Propane	7.1740	1.9847	
I Butane	0.8705	0.2861	
N Butane	2.2867	0.7239	
I Pentane	0.5375	0.1974	
N Pentane	0.5432	0.1977	
Hexanes +	0.7852	0.3441	

Nitrogen	1.4591
CO2	0.7996
Oxygen	0.0000
H2O	0.6600
CO	0.0000
H2S	0.0596
Hydrogen	0.0000
Helium	0.0000
Argon	0.0000

Total	100.0000	7.1987
--------------	----------	--------

Sample Comments:**Configuration Comments:**

Flaring Summary

battery	8/10/2021
Gipple Fed Com Tank Battery	369.40
Grand total	369.40

date

Data table:
flare_report_data (2)
Colors:
All values

battery

Sum(TOTAL FLARE (HP + LP))

District I1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720**District II**811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720**District III**1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170**District IV**1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 42236

QUESTIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 42236
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	[30-025-46668] GIPPLE FEDERAL COM #114H
Incident Facility	Not answered.

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a notification of a major venting and/or flaring	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	72
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	08/09/2021
Time venting and/or flaring was discovered or commenced	06:00 AM
Time venting and/or flaring was terminated	06:00 PM
Cumulative hours during this event	5

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Midstream Emergency Maintenance Gas Compressor Station Natural Gas Flared Released: 369 Mcf Recovered: 0 Mcf Lost: 369 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting and/or flaring a result of downstream activity	No
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	Lucid Energy, our midstream provider, saw numerous gas compressor stations go down across the LEA field. Due to this Tap Rock flare numbers spiked larger than regulated volumes. Once Lucid can solve their issue, Tap Rock should see normal operations. No timetable has been given to fix this issue.
Steps taken to limit the duration and magnitude of venting and/or flaring	Lucid Energy, our midstream provider, saw numerous gas compressor stations go down across the LEA field. Due to this Tap Rock flare numbers spiked larger than regulated volumes. Once Lucid can solve their issue, Tap Rock should see normal operations. No timetable has been given to fix this issue.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Lucid Energy, our midstream provider, saw numerous gas compressor stations go down across the LEA field. Due to this Tap Rock flare numbers spiked larger than regulated volumes. Once Lucid can solve their issue, Tap Rock should see normal operations. No timetable has been given to fix this issue.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 42236

CONDITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 42236
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
bramsey	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/16/2021