

GAS VOLUME STATEMENT**Spur Energy**

April, 2021

Meter #: 79410116

Name: Lakewood 3 Fed 14H

Closed Data

Artesia-East

Pressure Base: 14.650 psia

Temperature Base: 60.00 °F

HV Cond:

Meter Type: EFM

Contract Hr.: 8 AM

Status: In Service

WV Technique:

WV Method:

CO2	N2	H2O	H2S	O2	He	C1	C2	C3	I-C4	N-C4	I-C5	N-C5	C6+
6.067	5.675	0.000	1.9229	0.000	0.000	51.804	16.643	11.505	1.321	3.126	0.711	0.660	0.564
Tube I.D.		Interval		Tap Location		Tap Type		Atmos. Pressure		Calc. Method		Fpv Method	
3.068 in.		1 Hour		Upstream		Flange		12.950 psi		AGA3-1992		AGA8-Detail	

Day	Differential (In. H2O)	Pressure (psia)	Temperature (°F)	Hours Flow	Relative Density	Plate (inches)	Volume (Mcf)	Heating Value (Btu/scf)	Energy (MMBtu)	Edited
1	0.47	101.14	64.06	0.13	0.9279	2.000	0.70	1346.10	0.94	No
2	0.30	99.76	68.49	0.76	0.9279	2.000	3.96	1346.10	5.34	No
3	0.39	100.40	67.88	2.12	0.9279	2.000	12.56	1346.10	16.91	No
4	0.50	99.01	68.76	3.16	0.9279	2.000	20.89	1346.10	28.11	No
5	0.64	84.57	76.64	3.43	0.9279	2.000	23.29	1346.10	31.35	No
6	1.22	84.56	73.59	5.42	0.9279	2.000	48.07	1346.10	64.71	No
7	1.54	84.60	75.33	6.86	0.9279	2.000	70.70	1346.10	95.16	No
8	1.71	84.47	81.66	7.96	0.9279	2.000	85.21	1346.10	114.70	No
9	1.56	84.63	77.14	8.80	0.9279	2.000	90.09	1346.10	121.27	No
10	1.53	84.75	73.54	8.69	0.9279	2.000	88.39	1346.10	118.99	No
11	1.43	84.93	80.08	8.89	0.9279	2.000	87.31	1346.10	117.53	No
12	1.31	85.32	72.38	10.28	0.9279	2.000	98.05	1346.10	131.99	No
13	1.20	85.69	73.67	10.79	0.9279	2.000	98.70	1346.10	132.86	No
14	1.29	87.68	70.71	12.87	0.9279	2.000	124.23	1346.10	167.23	No
15	1.45	88.67	65.77	13.35	0.9279	2.000	137.46	1346.10	185.04	No
16	1.55	89.56	71.39	15.51	0.9279	2.000	166.14	1346.10	223.64	No
17	1.52	86.98	68.77	16.79	0.9279	2.000	176.54	1346.10	237.63	No
18	1.52	88.60	69.36	17.43	0.9279	2.000	185.28	1346.10	249.41	No
19	1.46	88.46	74.54	18.49	0.9279	2.000	191.10	1346.10	257.24	No
20	1.46	87.68	68.99	18.71	0.9279	2.000	193.57	1346.10	260.56	No
21	1.53	89.02	68.59	19.80	0.9279	2.000	210.84	1346.10	283.82	No
22	1.51	89.21	75.59	20.03	0.9279	2.000	211.05	1346.10	284.09	No
23	1.54	89.89	77.14	20.16	0.9279	2.000	214.42	1346.10	288.63	No
24	1.32	86.77	80.50	22.36	0.9279	2.000	220.17	1346.10	296.38	No
25	1.27	87.20	82.96	22.94	0.9279	2.000	222.47	1346.10	299.47	No
26	1.45	92.79	80.68	23.36	0.9279	2.000	249.89	1346.10	336.38	No
27	1.45	92.85	81.77	23.28	0.9279	2.000	249.67	1346.10	336.08	No
28	1.69	95.16	74.48	23.46	0.9279	2.000	276.26	1346.10	371.87	No
29	1.65	92.29	67.27	23.53	0.9279	2.000	272.67	1346.10	367.04	No
30	1.86	96.96	78.30	23.56	0.9279	2.000	293.68	1346.10	395.32	No
TOTAL	1.49	89.66	74.69	412.91	0.9279		4,323.38		5,819.71	

Name of well or facility	Lat	Long	Daily Volume of Flared Natural Gas (MCF/D)	Commencement	Duration	Proposed Remedy
SHELBY 23 TANK BATTERY	32.636495	-104.449015	1314 MCF/D	8/10/2021	Continuous	ACO Requested
ROSS RANCH 09.13.14 BATTERY	32.636187	-104.47781	1314 MCF/D	8/10/2021	Continuous	ACO Requested
OSAGE BOYD 15 FED 09.12.13.14 TANK BATTERY	32.652839	-104.478905	992 MCF/D	8/10/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM NORTH BATTERY	32.625808	-104.469155	2869 MCF/D	8/10/2021	Continuous	ACO Requested
LAKEWOOD FEDERAL COM SOUTH BATTERY	32.608649	-104.479201	1680 MCF/D	8/10/2021	Continuous	ACO Requested
DORAMI 33 FEDERAL COM 2H.4H.9H TANK BATTERY	32.614416	-104.478493	622 MCF/D	8/10/2021	Continuous	ACO Requested
HUBER 10, 11, 12 FEDERAL OIL TANK BATTERY	32.610648	-104.472851	799 MCF/D	8/10/2021	Continuous	ACO Requested
JG STATE 16 7 TANK BATTERY	32.8357887	-103.7768707	93 MCF/D	8/10/2021	Continuous	Gas Rerouted
JG STATE 16 1 TANK BATTERY	32.8284187	-103.7790146	131 MCF/D	8/10/2021	Continuous	Gas Rerouted
NEWCASTLE 6 FEDERAL COM TANK BATTERY	32.8592453	-104.0196991	94 MCF/D	8/10/2021	Continuous	Gas Rerouted

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 42413

QUESTIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 42413
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2122833205] Lakewood Federal Com South Tank Battery

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	No
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a notification of a major venting and/or flaring	Yes, major venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	52
Nitrogen (N2) percentage, if greater than one percent	6
Hydrogen Sulfide (H2S) PPM, rounded up	19,229
Carbon Dioxide (CO2) percentage, if greater than one percent	6
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	08/10/2021
Time venting and/or flaring was discovered or commenced	12:00 AM
Time venting and/or flaring was terminated	12:00 AM
Cumulative hours during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Other (Specify) Natural Gas Flared Released: 1,680 Mcf Recovered: 0 Mcf Lost: 1,680 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting and/or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	3rd party take away refusal due to capacity restraints.
Steps taken to limit the duration and magnitude of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Executed contract with midstream company to gather gas by 12/1/2021.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 42413

CONDITIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947
	Action Number: 42413
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
schapman01	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/17/2021