# **Monthly Meter Analysis**

July, 2021

Oxygen, O2

Carbon Monoxide, CO Hydrogen, H2 Helium, He Argon, Ar



Meter #: 718444-00 Name: Buckeye 1 St. #1 Sample

Date: 06/22/2021

Type: Spot

Pressure: Temperature: 38.0 H2O: 80.0 H2S:

lbs/mm ppm

Component	Mole %	Liquid Content	Mass %
Carbon Dioxide, CO2	0.2933		0.5390
Nitrogen, N2	3.1189		3.6485
Methane, C1	71.1785		47.6835
Ethane, C2	12.9407	3.4758	16.2489
Propane, C3	6.6296	1.8344	12.2075
Isobutane, iC4	0.7483	0.2459	1.8163
n-Butane, nC4	0.0000	0.0000	0.0000
Isopentane, iC5	0.9693	0.3560	2.9204
n-Pentane, nC5	1.2546	0.4567	3.7799
Hexanes Plus, C6+	2.8668	1.2564	11.1560
Water, H2O			
Hydrogen Sulfide, H2S			

Property	Total Sample
Pressure Base Temperature Base Relative Density HV, Dry @ Base P,T HV, Sat @ Base P, T HV, Sat @ Sample P, T Fws Factor	14.730 60.00 0.8303 1384.65 1360.42
Cricondentherm HCDP @ Sample Pressure Free Water GPM Stock Tank Condensate Brls/mm 26 # RVP Gasoline Testcar Permian Testcar Midcon	3.230 1.618 1.088 1.646

Totals	100.0000	7.6252	100.0000

Page 1

## Printed 8/17/2021

# Daily Battery Production Totals Fasken Oil and Ranch, LTD.

## August 2021

		Gas	Water
8/1	8.0	15.0	0.0
8/2	0.8	22.0	0.0
8/3	0.8	22.0	0.0
8/4	1.3	19.0	0.0
8/5	0.8	13.0	0.0
8/6	1.3	19.0	0.0
8/7	1.7	21.0	0.0
8/8	1.3	23.0	0.0
8/9	1.3	21.0	0.0
8/10	1.3	19.0	0.0
8/11	1.3	16.0	0.0
8/12	1.7	19.0	0.0
8/13	1.7	21.0	0.0
8/14	1.7	20.0	0.0
8/15	1.3	16.0	0.0
8/16	1.3	21.0	0.0
Total	20	307	0
Avg.	1	19	0

Fasken Oil and Ranch, LTD. - 17

**Days** 

Total

Avg.

Report Based On:

Date Range: 8/1/2021 through 8/17/2021

Batteries selected based on the following Report Menu selections:

Wells = Buckeye 1 State # 1.

Daily Production is the daily sum of the daily gross battery production.

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 41941

Q	UESTIONS	
Operator:		OGRID:
FASKEN OIL & RANCH LTD 6101 Holiday Hill		151416 Action Number:
Midland, TX 79707		41941
		Action Type:  [C-129] Venting and/or Flaring (C-129)
QUESTIONS		, , , ,
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve	these issues before continuing wit	h the rest of the questions.
Incident Well	[30-025-36333] BUCKEYE	1 STATE #001
Incident Facility	Not answered.	
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers at	nd may provide addional guidance T	
Was or is this venting and/or flaring caused by an emergency or malfunction	No	
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes	
Is this considered a submission for a notification of a major venting and/or flaring	Yes, minor venting and/or	flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v	enting and/or flaring that is or may	be a major or minor release under 19.15.29.7 NMAC.
Was there or will there be at least 50 MCF of natural gas vented and/or flared	Yes	
during this event		
Did this venting and/or flaring result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a	No	
surface, a watercourse, or otherwise, with reasonable probability, endanger public	No	
health, the environment or fresh water  Was the venting and/or flaring within an incorporated municipal boundary or		
withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Institution of Charlet in existence		
Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.	T	
Methane (CH4) percentage	71	
Nitrogen (N2) percentage, if greater than one percent	3	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent		
	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required spec		
If you are venting and/or flaring because of Pipeline Specification, please provide the required specification. Methane (CH4) percentage quality requirement		
	ifications for each gas.	
Methane (CH4) percentage quality requirement	ifications for each gas.  Not answered.	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement	ifications for each gas.  Not answered.  Not answered.	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement	ifications for each gas.  Not answered.  Not answered.  Not answered.	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement  Carbon Dioxide (C02) percentage quality requirement  Oxygen (02) percentage quality requirement	ifications for each gas.  Not answered.  Not answered.  Not answered.  Not answered.	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement  Carbon Dioxide (C02) percentage quality requirement	ifications for each gas.  Not answered.  Not answered.  Not answered.  Not answered.	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement  Carbon Dioxide (C02) percentage quality requirement  Oxygen (02) percentage quality requirement	ifications for each gas.  Not answered.  Not answered.  Not answered.  Not answered.	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement  Carbon Dioxide (C02) percentage quality requirement  Oxygen (02) percentage quality requirement	Not answered.  Not answered.  Not answered.  Not answered.  Not answered.  Not answered.	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement  Carbon Dioxide (C02) percentage quality requirement  Oxygen (02) percentage quality requirement  Date(s) and Time(s)  Date venting and/or flaring was discovered or commenced	ifications for each gas.  Not answered.  Not answered.  Not answered.  Not answered.  Not answered.  08/17/2021	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement  Carbon Dioxide (C02) percentage quality requirement  Oxygen (02) percentage quality requirement  Date(s) and Time(s)  Date venting and/or flaring was discovered or commenced  Time venting and/or flaring was discovered or commenced	ifications for each gas.  Not answered.  Not answered.  Not answered.  Not answered.  Not answered.  08/17/2021  06:00 AM	
Methane (CH4) percentage quality requirement  Nitrogen (N2) percentage quality requirement  Hydrogen Sufide (H2S) PPM quality requirement  Carbon Dioxide (C02) percentage quality requirement  Oxygen (02) percentage quality requirement  Date(s) and Time(s)  Date venting and/or flaring was discovered or commenced  Time venting and/or flaring was terminated	Not answered. 08/17/2021 06:00 AM 06:30 PM	

Not answered.

Natural Gas Vented (Mcf) Details

Natural Gas Flared (Mcf) Details	Cause: Midstream Scheduled Maintenance   Gas Plant   Natural Gas Flared   Released: 100 Mcf   Recovered: 0 Mcf   Lost: 100 Mcf
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity		
Was or is this venting and/or flaring a result of downstream activity	Yes	
Date notified of downstream activity requiring this venting and/or flaring	08/12/2021	
Time notified of downstream activity requiring this venting and/or flaring	03:44 PM	

Steps and Actions to Prevent Waste		
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True	
Please explain reason for why this event was beyond your operator's control	DCP has schedule maintenance	
Steps taken to limit the duration and magnitude of venting and/or flaring	DCP needs to do maintenance - we assist as needed	
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Cannot control when maintenance is needed	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 41941

### **CONDITIONS**

Operator:	OGRID:	
FASKEN OIL & RANCH LTD	151416	
6101 Holiday Hill	Action Number:	
Midland, TX 79707	41941	
	Action Type:	
	[C-129] Venting and/or Flaring (C-129)	

#### CONDITIONS

Created By	Condition	Condition Date
vvasquez	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/23/2021