Jessica Zemen Lead Environmental Specialist, Field Support



6301 Deauville Blvd. Midland, TX 79706 432-530-9187 jessicazemen@chevron.com

## Volume for Emission Event:

3. Time of Event						1. Ven		2. Calculating Yolumetri Estimation	c Release Ra	te for YRU Releases Inca		3. Gaseous Volumet Rate (scf/hr or scf/e		
Date of discove	Discovery or Scheduled Activity	start of eventor Schedul	Start of Event or Schedule	of event or Scheduled Activit	actual end of event or Scheduled	Duration of Event in Hou	Vent o		Is Volume Metered, Estimated or Otherwise	Daily Production (BOPD o MMscf/da	Is a site-specific GOR or Cond Tank Vent Rate known?	GOR (sef gas / barrel oil) or Cond Tanl	Value	Units 🔻
8/23/2021	9:30:00	8/23/2021	9:30:00	8/23/2021	9:44:00	0.23	Fla	are					102	msof/event

## Gas Analysis for Emission Event:

I. Gas Sample Selection	Is a gas analysis for this release of gas available?	
	Sample ID #	83968.041
	Sample Date	10/17/2018
	Sample Description	Inlet Gas Analysis
	Low Heating Value (BTU/SCF)	1353
	H2S (molt) <sup>[1]</sup>	0.001
	Mitrogen (mol2)	0.617
	CO <sub>2</sub> (mol2)	0.155
	Methane (mol2)	75.440
	Ethane (mol2)	11.622
	Propane (mol2)	5.382
II. Gas Sample Char-	Iso-Butane (mol\$)	0.961
acteristics	N-Butane (mol2)	2.071
	iso-Pentane (mol2)	0.690
	n-Pentane (mol2)	0.794
	Heranes (molt)	0.915
	Heptanes + (mol2)	1.348
	2,2,4-trimethypentane (mol%)	
	n-Herane (mol2)	0.172
	Benzene (mol2)	0.018
	Ethyl-Benzene (mol2)	0.002
	Xylene (mol2)	0.016
	Toluene (mol2)	0.042

Operator:

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 45653

#### **QUESTIONS**

OGRID:

CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	45653
	Action Type:  [C-129] Venting and/or Flaring (C-129)
QUESTIONS	
Prerequisites	
Any messages presented in this section, will prevent submission of this application. Please resolve	these issues before continuing with the rest of the questions.
Incident Well	Not answered.
Incident Facility	[fAPP2123739359] HY NM Section 10 CTB and Compressor Stations
Determination of Reporting Requirements	
Answer all questions that apply. The Reason(s) statements are calculated based on your answers a	
Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a notification of a major venting and/or flaring	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v	renting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.
Was there or will there be <b>at least 50 MCF</b> of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No
Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.
Representative Compositional Analysis of Vented or Flared Natural Gas	
Please provide the mole percent for the percentage questions in this group.	т
Methane (CH4) percentage	24
Nitrogen (N2) percentage, if greater than one percent	0
Hydrogen Sulfide (H2S) PPM, rounded up	10
Carbon Dioxide (C02) percentage, if greater than one percent	0
Oxygen (02) percentage, if greater than one percent	0

Date(s) and Time(s)					
Date venting and/or flaring was discovered or commenced	08/23/2021				
Time venting and/or flaring was discovered or commenced	09:30 AM				
Time venting and/or flaring was terminated	09:44 AM				
Cumulative hours during this event	0				

Not answered.

Not answered.

Not answered.

Not answered.

Not answered.

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.

Methane (CH4) percentage quality requirement

Nitrogen (N2) percentage quality requirement

Oxygen (02) percentage quality requirement

Hydrogen Sufide (H2S) PPM quality requirement

Carbon Dioxide (C02) percentage quality requirement

lf you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas

Natural Gas Flared (Mcf) Details	Cause: Equipment Failure   Gas Compressor Station   Natural Gas Flared   Released: 102 Mcf   Recovered: 0 Mcf   Lost: 102 Mcf ]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity				
Was or is this venting and/or flaring a result of downstream activity	Not answered.			
Date notified of downstream activity requiring this venting and/or flaring	Not answered.			
Time notified of downstream activity requiring this venting and/or flaring	Not answered.			

Steps and Actions to Prevent Waste				
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True			
Please explain reason for why this event was beyond your operator's control	The compressor station shutdown due to a main motor feedback failure. This shutdown resulted in a flaring event.			
Steps taken to limit the duration and magnitude of venting and/or flaring	All of the facilities and emissions control devices at this site are operating as designed and, where applicable, are authorized. Chevron field personnel will execute practicable measures to minimize emissions.			
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Corrective measures focused on reducing gas production as quickly and safely as possible to minimize the duration and volume of gas flared			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 45653

### **CONDITIONS**

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	45653
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

#### CONDITIONS

Created By	Condition	Condition Date
jzemen	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/31/2021