RGas Composition and Properties

Effective August 1, 2021 09:00 - January 18, 2038 21:14

Source #: 2.10.8

Name: Cypress 34 B CDP



Component	Mole %	Liquid Content	Mass %	Property	Total Sample	C6 Plus Fraction
Carbon Dioxide, CO2	0.0880		0.1738	Pressure Base	14.650	
Nitrogen, N2	0.8840		1.1112	Temperature Base	60.00	
Methane, C1	75.2310		54.1562	HCDP @ Sample Pressure)	
Ethane, C2	12.3790	3.3158	16.7026	Cricondentherm		
Propane, C3	6.2470	1.7237	12.3608	HV, Dry @ Base P, T	1333.80	4755.9000
iso-Butane, iC4	0.9080	0.2976	2.3681	HV, Sat @ Base P, T	1311.00	
n-Butane, nC4	2.1280	0.6719	5.5500	HV, Sat @ Sample P, T	1323.67	
iso-Pentane, iC5	0.5130	0.1879	1.6608	Relative Density	0.7750	0.66406
n-Pentane, nC5	0.5650	0.2051	1.8292			
Neo-Pentane, NeoC5						
Hexanes Plus, C6+	1.0570	0.4353	4.0873			
Water, H2O Hydrogen Sulfide, H2S Oxygen, O2 Carbon Monoxide, CO Hydrogen, H2 Helium, He Argon, Ar				C6+: 100		

Totals 100.0000 6.8380 100.0000

SampleDate: 08/18/2021

 Date:
 08/18/2021
 Pressure:
 103.7

 Type:
 Spot
 Temperature:
 98.2

Tech: TT H2O: lbs/mm H2S: 0 ppm

Remarks:

Analysis

Cylinder:

Tech: GL

Remarks:

Flaring Summary

	11/24/2021
battery	Sum(TOTAL F
Cypress 34 B Tank Battery	59.00
Grand total	59.00

date » (Column Names)

Data table:
flare_report_data (2)
Colors:
All values

battery

Sum(TOTAL FLARE (HP + LP))

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 64923

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401		OGRID: 372043
523 Park Point Drive		
Golden, CO 80401		Action Number:
		64923
		Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve	these issues before continuing with	n the rest of the questions.
Incident Well	Not answered.	
Incident Facility	[fAPP2126031208] Cypress	s B CTB
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers a		
Was or is this venting and/or flaring caused by an emergency or malfunction	No	
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No	
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or f	flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during	venting and/or flaring that is or may	be a major or minor release under 19.15.29.7 NMAC.
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes	
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Equipment Involved		
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.	_	
Methane (CH4) percentage	75	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required spe	cifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	
	•	
Date(s) and Time(s)		
Date venting and/or flaring was discovered or commenced	11/24/2021	
Time venting and/or flaring was discovered or commenced	06:00 AM	
Time venting and/or flaring was terminated	06:00 PM	
Cumulative hours during this event	1	
Measured or Estimated Volume of Vented or Flared Natural Gas		

Not answered.

Natural Gas Vented (Mcf) Details

Natural Gas Flared (Mcf) Details	Cause: Normal Operations Producing Well Natural Gas Flared Released: 59 Mcf Recovered: 0 Mcf Lost: 59 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity			
Was or is this venting and/or flaring a result of downstream activity	Not answered.		
Was notification of downstream activity received by you or your operator	Not answered.		
Downstream OGRID that should have notified you or your operator	Not answered.		
Date notified of downstream activity requiring this venting and/or flaring	Not answered.		
Time notified of downstream activity requiring this venting and/or flaring	Not answered.		

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	False
Please explain reason for why this event was beyond your operator's control	Not answered.
Steps taken to limit the duration and magnitude of venting and/or flaring	Tap Rock saw higher flare due to the make up regulator to the heater treater letting more gas in. The back pressure valve to the heater treater was relieving the pressure to the VRT and then to the tanks.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Tap Rock is analyzing this location and the equipment on location to verify the facility can capture all excess gas. If flaring continues Tap Rock will alter the facility by placing additional gas takeaway equipment.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 64923

CONDITIONS

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	64923
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
bramsey	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	12/3/2021