District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2201252570
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party XTO Energy			OGRID 4	OGRID 5380		
Contact Name Shelby Pennington			Contact Te	Contact Telephone 281-723-9353		
Contact emai	Contact email shelby.g.pennington@exxonmobil.com			Incident #	(assigned by OCD)	
Contact mailing address 6401 Holiday Hill Rd Bldg 5, Midland, Texa		nd, Texas, 79707				
			Location	of Release So	ource	
Latitude 32.1	14419			Longitude _	-104.00913	
			(NAD 83 in dec	cimal degrees to 5 decim	nal places)	
Site Name Co	orral Canyor	n 8-32 Fed 163H	·	Site Type P	roduction Well	
Date Release	Discovered	12/29/2021		API# (if app	licable)	
TT '. T		Tr 1'			,	
Unit Letter	Section	Township	Range	Coun		
K	08	25S	29E	Edd	У	
Surface Owner	r: State	➤ Federal ☐ Ti	ribal Private (A	Name:)
						,
			Nature and	l Volume of F	Release	
				calculations or specific		
Crude Oil		Volume Release			Volume Recove	,
Produced	Water	Volume Release			Volume Recovered (bbls)	
		l .	tion of total dissolv water >10,000 mg	` ,	Yes No	
Condensa	ite	Volume Release			Volume Recove	ered (bbls)
☐ Natural Gas Volume Released (Mcf)			Volume Recove	ered (Mcf)		
Control Volume/Weight Released (provide units)		units)	Volume/Weight Recovered (provide units)			
Frac fluid 30 BBLS			29.75			
Cause of Rele	ease Corrosi	on caused a hose of	connection on a fra	ac pump to release	fluids both into co	ontainment and onto pad. All free
Cause of Release Corrosion caused a hose connection on a frac pump to release fluids both into containment and onto pad. All free fluids were recovered. A third-party contractor has been retained for remediation purposes.						

Received by OCD: 1/12/2022 2:45:15 PM Form C-141 State of New Mexico Page 2 Oil Conservation Division

	I uge z oj
Incident ID	NAPP2201252570
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the respon	nsible party consider this a major release?
release as defined by	A release equal to or greater than 25 barre	ls.
19.15.29.7(A) NMAC?		
Yes No		
If YES, was immediate no	otice given to the OCD? By whom? To wl	nom? When and by what means (phone, email, etc)?
Yes, by Garrett Green to I	Mike Bratcher, Victoria Venegas, and Rob	Hamlet on Wednesday, December 29, 2021 6:48 PM via email.
Ļ		
	Initial R	esponse
The responsible	party must undertake the following actions immediate	y unless they could create a safety hazard that would result in injury
* The source of the rele	ease has been stopped.	
	s been secured to protect human health and	the anxironment
1	•	
		likes, absorbent pads, or other containment devices.
-	ecoverable materials have been removed an	· · · · ·
	d above have <u>not</u> been undertaken, explain	why:
NA		
D 10.15.20.0 D (4) ND	W.C.1	
		emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred
		please attach all information needed for closure evaluation.
I hereby certify that the info	rmation given above is true and complete to the	best of my knowledge and understand that pursuant to OCD rules and
		fications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have
failed to adequately investig	ate and remediate contamination that pose a three	at to groundwater, surface water, human health or the environment. In
addition, OCD acceptance o and/or regulations.	f a C-141 report does not relieve the operator of	responsibility for compliance with any other federal, state, or local laws
Shelby G	. Pennington	Title: Environmental Manager
Printed Name:		Title:
Signature:	elle territo	Date:1/12/22
email: shelby.g.penningto	on@exxonmobil.com	Telephone:
eman.		Telephone.
OCD Only		
_	Magne	D 4
Received by: Ramona	LIVIAICUS	Date: 01/12/2022

Location:	Corral Canyon 8-32 Fed 163H				
Spill Date:	12/29/2021				
	Area 1		- 1		
Approximate Are	ea =	140.36	cu.ft.		
	VOLUME OF LEAK				
Total Crude Oil =		0.00	bbls		
Total Frac fluid =		25.00	bbls		
	Area 2				
Approximate Are	ea =	1101.00	00 sq. ft.		
Average Saturati	on (or depth) of spill =	0.50	inches		
		**			
Average Porosity	Factor =	0.03			
	VOLUME OF LEAK				
Total Crude Oil =		0.00	bbls		
Total Frac fluid =		5.00	bbls		
	TOTAL VOLUME OF LEAK				
Total Crude Oil =	•	0.00	bbls		
Total Frac fluid =	· · · · · · · · · · · · · · · · · · ·	30.00	bbls		
	TOTAL VOLUME RECOVERED				
Total Crude Oil =	·	0.00	bbls		
Total Frac fluid =	:	29.75	bbls		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 72068

CONDITIONS

Operator:	OGRID:
XTO ENERGY, INC	5380
,	Action Number:
Midland, TX 79707	72068
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	1/12/2022