



Certificate of Analysis

Number: 6030-21080194-010A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Alex Batista
Taprock
602 Park Point Drive
Ste. 200
Golden, CO 80401

Aug. 25, 2021

Station Name: Yada Fed Com 135
Station Number: 7060303
Sample Point: Meter run
Formation: Spot
County: Lea
Type of Sample: Spot-Cylinder
Heat Trace Used: N/A
Sampling Method: Fill and Purge
Sampling Company: SPL

Sampled By: James Hill
Sample Of: Gas Spot
Sample Date: 08/17/2021 10:45
Sample Conditions: 139.8 psig, @ 128.6 °F Ambient: 90 °F
Effective Date: 08/17/2021 10:45
Method: GPA-2261M
Cylinder No: 5030-02476
Instrument: 70104124 (Inficon GC-MicroFusion)
Last Inst. Cal.: 07/08/2021 0:00 AM
Analyzed: 08/24/2021 09:52:07 by KNF

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia
Hydrogen Sulfide	NIL	0.20000	0.290	
Nitrogen	1.282	1.29614	1.546	
Carbon Dioxide	1.424	1.43976	2.698	
Methane	71.822	72.64287	49.632	
Ethane	11.270	11.39915	14.597	3.062
Propane	6.652	6.72799	12.635	1.862
Iso-Butane	1.011	1.02245	2.531	0.336
n-Butane	2.447	2.47455	6.125	0.783
Iso-Pentane	0.763	0.77151	2.371	0.283
n-Pentane	0.705	0.71326	2.192	0.260
Hexanes	0.612	0.61889	2.271	0.256
Heptanes	0.468	0.47294	2.018	0.219
Octanes	0.182	0.18448	0.897	0.095
Nonanes Plus	0.036	0.03601	0.197	0.020
	98.674	100.00000	100.000	7.176

Calculated Physical Properties

Calculated Molecular Weight	Total	C9+
Compressibility Factor	23.48	128.26
Relative Density Real Gas	0.9955	
	0.8141	4.4283

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.73 psia & 60°F

Real Gas Dry BTU	1358.2	7012.5
Water Sat. Gas Base BTU	1335.1	6890.4
Ideal, Gross HV - Dry at 14.73 psia	1352.0	7012.5
Ideal, Gross HV - Wet	1328.5	6890.4

Comments: H2S Field Content 2000 ppm
CO2 1.3%
Mcf/dady 2179.5

Data reviewed by: Eric Ramirez, Analyst

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

Flaring Summary

battery	7/22/2022
	Sum(TOTAL F...
Yada CTB A	79.40
Grand total	79.40

date » (Column Names)

Data table:
flare_report_data (2)
Colors:
All values

battery

Sum(TOTAL FLARE (HP + LP))

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 129028

DEFINITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 129028
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.
--

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 129028

QUESTIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 129028
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites	
<i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	Not answered.
Incident Facility	[fAPP2126033248] Yada CTB A

Determination of Reporting Requirements	
<i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas	
<i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	73
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 129028

QUESTIONS (continued)

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 129028
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	07/22/2022
Time vent or flare was discovered or commenced	06:00 AM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	2

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure Separator Natural Gas Flared Released: 79 Mcf Recovered: 0 Mcf Lost: 79 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	Tap Rock saw a higher-than-normal flare volume due to downtime on of a VRU unit on location. The malfunction of the equipment is still under investigation. Tap Rock also saw flare volumes due to flash gas coming off of the tanks and an excess amount of oxygen at the tank level. The amount of oxygen does not meet pipeline quality specifications for our midstream provider. Tap Rock is analyzing this location and the equipment on location to verify the facility can capture all excess gas. If flaring continues Tap Rock will alter the facility by placing additional gas takeaway equipment.
Steps taken to limit the duration and magnitude of vent or flare	Tap Rock saw a higher-than-normal flare volume due to downtime on of a VRU unit on location. The malfunction of the equipment is still under investigation. Tap Rock also saw flare volumes due to flash gas coming off of the tanks and an excess amount of oxygen at the tank level. The amount of oxygen does not meet pipeline quality specifications for our midstream provider. Tap Rock is analyzing this location and the equipment on location to verify the facility can capture all excess gas. If flaring continues Tap Rock will alter the facility by placing additional gas takeaway equipment.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Tap Rock saw a higher-than-normal flare volume due to downtime on of a VRU unit on location. The malfunction of the equipment is still under investigation. Tap Rock also saw flare volumes due to flash gas coming off of the tanks and an excess amount of oxygen at the tank level. The amount of oxygen does not meet pipeline quality specifications for our midstream provider. Tap Rock is analyzing this location and the equipment on location to verify the facility can capture all excess gas. If flaring continues Tap Rock will alter the facility by placing additional gas takeaway equipment.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 129028

ACKNOWLEDGMENTS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 129028
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 129028

CONDITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 129028
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
bramsey	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	7/27/2022