

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	nAPP2302538491
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party Silverback Operating	OGRID 330968
Contact Name Mark Ritchie	Contact Telephone 210-874-2406
Contact email mritchie@silverbackexp.com	Incident # (assigned by OCD)
Contact mailing address 108 S. 4th st Artesia, NM 88211	

### Location of Release Source

Latitude 32.722668 Longitude -104.360797  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Shudde 27 CTB	Site Type Central Tank Battery
Date Release Discovered 1-13-2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	26	18S	26E	Eddy

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: HINKLE, R R COMPANY, INC & SCHERTZ, MORRIS E)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 20	Volume Recovered (bbls) 20
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Water hauler left water load line valve open. Mistake was caught shortly after by next truck who began to recover standing fluid.

Form C-141

State of New Mexico  
Oil Conservation Division

Page 2

Incident ID	nAPP2302538491
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?  
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?  	

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:  Standing fluid was removed so there was no need to contain the released material, and release was contained mostly to the lease road where fencing off would have prevented egress in an emergency event.	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Mark Ritchie</u> Signature: <u></u> email: <u>mritchie@silverbackexp.com</u>	Title: <u>HSE Manager</u> Date: <u>1/25/2023</u> Telephone: <u>210-874-2406</u>
<b><u>OCD Only</u></b> Received by: <u>Jocelyn Harimon</u> Date: <u>01/30/2023</u>	



**SILVERBACK**  
EXPLORATION

Volume Justification Sheet – Silverback Form 018

### Volume Justification

This form is to be used to convey justification of spill volumes in the event of a release. Clearly indicate by calculations or description in the space provided below.

**Justification:** Run ticket from water hauler who removed standing fluid showing 20bbls.

 <b>Alliance Trucking, LLC</b> PO Box 1599 Artesia, New Mexico, 88211 (575) 736-7468		<b>DELIVERY TICKET:</b> <b>Nº 308880</b>	
Company: <u>Silver Back</u>		Date: <u>01-13-2023</u>	
Lease: <u>Schodde 27 CTB</u>		Ordered By: <u>Rafael</u>	
Rig #: _____ AFE #: _____		County: <u>Eddy County NM</u>	

FW Ticket #	BBLS	RATE	CHARGE
BW Ticket #	BBLS		
SWD Ticket # <u>955-16349</u>	BBLS <u>120</u>	<u>.90</u>	<u>108.00</u>
Chemical	GLNS		
Start Time <u>8:00 am</u> End Time <u>8:00 am</u> Total Hours <u>6 hrs</u>		<u>9.00</u>	<u>570.00</u>
DESCRIPTION			
<u>Drive to location and suck all the water from the ground clean the best and top off from the frack pond and take it to public SWD and drive back home (20 BBL spill)</u>			
SUBTOTAL			<u>678.00</u>
TAX			
Driver: <u>Donel Labann</u>	Trk #: <u>68</u>	TOTAL	

Received By: \_\_\_\_\_ ☐ Pump Truck ☒ Vacuum Truck

**Approved by:** Mark Ritchie

**Date:** 1/25/2023

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 179572

CONDITIONS

Operator: Silverback Operating II, LLC IH10 West, Suite 201 San Antonio, TX 78257	OGRID: 330968
	Action Number: 179572
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	1/30/2023