

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2303737335
District RP	
Facility ID	fAPP2135655250
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Bob Hall	Contact Telephone: 432-682-3753
Contact email: bhall@btaoil.com	Incident # (assigned by OCD) nAPP2303737335
Contact mailing address: 104 S. Pecos St., Midland, TX 79701	

Location of Release Source

Latitude: 32.06221 Longitude: -103.61441

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Mesa B West – Burned Water Transfer Poly Line	Site Type: Tank Battery
Date Release Discovered: 2/5/2023	API# (if applicable) Nearest well:

Unit Letter	Section	Township	Range	County
C	7	26S	33E	Lea

Surface Owner: State Federal Tribal Private (Name:)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 56 BBL	Volume Recovered (bbls) 1 BBL
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Gas feed line ruptured and caused a fire that burned the 8" poly line used for water transfer.
Recovered 1 BW.

(Spill Calculation Spreadsheet attached.)

Incident ID	nAPP2303737335
District RP	
Facility ID	fAPP2135655250
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Volume of release exceeded 25 BBL fluid. This release was the result of a fire.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice was provided by NOR filed on 2/6/2023 via the NMOCD Permitting Website.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: Bob Hall Title: Environmental Manager Signature: <u>Bob Hall</u> Date: 2/14/2023 email: bhall@btaoil.com Telephone: 432-682-3753
<u>OCD Only</u> Received by: <u>Jocelyn Harimon</u> Date: <u>02/14/2023</u>



Release Volume Calculator

This calculator estimates a spill volume based on the size and estimated saturation of the spill.

Location/Site Name Mesa B West Water Transfer Line
GPS Coordinates 32.06221,-103.61441
Spill Date and Time 2/5/2023

Instructions: Input the spill parameters (dimensions) in **blue** text, and the spreadsheet calculates a potential spill volume. Other parameters can be changed as appropriate.

Area 16,800 square feet
 Saturation (or depth) 1.5 inches
 Percent Hydrocarbon 0 % Hydrocarbon (0-100)
 Porosity (choose one) 0.15

Saturated Soil Volume 77.78 cubic yards

Total Hydrocarbon (oil)	0.00 barrels
Total Produced Water	56.10 barrels

Types of Soil	Porosity Factor
Sand	0.20
Clay	0.05
Clay/Silt-Sandy Mix	0.15
Caliche	0.03
Gravel	0.25
Unknown	0.25

Area Name (ft2)	Saturation Depth (in)	Total Oil (bbls)	Total Water (bbls)
Stained Area (16,800 sq ft)	1.5	0	56.1

Totals: 0 56.1
Total Volume Released: 56.1

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 185810

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 185810
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	2/16/2023