

Gas Composition and Properties

Effective December 1, 2022 00:00 - January 18, 2038 21:14

Source #: 100069
Name: South Baum Mm

| Component | Mole % | Liquid Content | Mass % | Property | Total Sample |
|------------------------|----------|----------------|----------|------------------------|--------------|
| Carbon Dioxide (CO2) | 0.4370 | | 0.8508 | Pressure Base | 14.65 |
| Nitrogen (N2) | 2.5735 | | 3.1892 | Temperature Base | 60 |
| Methane (C1) | 72.5436 | | 51.4829 | HCDP @ Sample Pressure | |
| Ethane (C2) | 12.4376 | 3.3207 | 16.5443 | Cricondentherm | |
| Propane (C3) | 7.1357 | 1.9626 | 13.9195 | HV, Dry @ Base P, T | 1308.32 |
| Isobutane (IC4) | 0.9095 | 0.2971 | 2.3385 | HV, Sat @ Base P, T | 1285.43 |
| n-Butane (NC4) | 2.1787 | 0.6857 | 5.6019 | HV, Sat @ Sample P, T | |
| Isopentane (IC5) | 0.5112 | 0.1866 | 1.6316 | Relative Density | 0.7833 |
| n-Pentane (NC5) | 0.5500 | 0.1990 | 1.7554 | | |
| Hexanes Plus (C6+) | 0.5832 | 0.2598 | 2.4748 | | |
| Argon (Ar) | | | | | |
| Carbon Monoxide (CO) | | | | | |
| Hydrogen (H2) | | | | | |
| Oxygen (O2) | | | | | |
| Helium (He) | | | | | |
| Water (H2O) | | | | | |
| Hydrogen Sulfide (H2S) | 0.1400 | | 0.2111 | C6+: 48 - 36 - 17 | |
| Totals | 100.0000 | 6.9130 | 100.0000 | | |

Sample

Date: 12/08/2022 Type: Spot
Tech: Paul T
Pressure: 34.0 psi Temp.: 64 °F
Gauge: H2O:
Atm. Pressure: H2S: 1,400 ppm

Remarks:

Analysis

Date: Instrument:
Tech: Cylinder:

Remarks:

*** End of Report ***

Enter data in shaded fields to calculate gas volumes released due to leak and blowdown of system.

| | | |
|---|------|--|
| Hours of leak = | 5.5 | Example: |
| Diameter of hole (inches) = | 0.25 | Leak for 4 (est) hours out of a 1/4 inch hole with line pressure of 750 psig |
| Upstream Pressure = | 22 | |
| Volume of gas (mcf/hr) loss is equal to the hole diameter squared times the upstream pressure absolute. * | | |

Volume of Gas Leaked = 12.62 Mcf

| | | |
|-----------------------------|-------|---|
| Footage of Pipe blowdown = | 20592 | |
| Initial line pressure = | 22 | Calculated factor for line pack = 7.843 |
| Diameter of Pipe (inches) = | 24 | |

Example:
Volume of Gas BlownDown = 161.51 Mcf
Loss of gas due to blowdown of 7 miles of 12 inch at initial pressure 51 psig

| | | | |
|----------------------------|------------|------------------------|---------|
| Total Volume of Gas Loss = | 174.13 Mcf | Reportable | 50 Mcf |
| | | Immediate Notification | 500 Mcf |

Comments:

Name : Amber Groves Title : Sr. Environmental Specialist

* Pipeline Rules of Thumb Handbook /2nd Edition

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 210537

DEFINITIONS

| | |
|--|--|
| Operator: TARGA MIDSTREAM SERVICES LLC 811 Louisiana Street Houston, TX 77002 | OGRID: 24650 |
| | Action Number: 210537 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

DEFINITIONS

| |
|--|
| For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: <ul style="list-style-type: none">• this application's operator, hereinafter "this operator";• venting and/or flaring, hereinafter "vent or flare";• any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";• the statements in (and/or attached to) this, hereinafter "the statements in this";• and the past tense will be used in lieu of mixed past/present tense questions and statements. |
|--|

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 210537

QUESTIONS

| | |
|--|--|
| Operator: TARGA MIDSTREAM SERVICES LLC 811 Louisiana Street Houston, TX 77002 | OGRID: 24650 |
| | Action Number: 210537 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

QUESTIONS

| | |
|---|--|
| Prerequisites <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i> | |
| Incident Well | Unavailable. |
| Incident Facility | [fAPP2123021777] Targa NM Gathering System |

| | |
|--|---|
| Determination of Reporting Requirements <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i> | |
| Was this vent or flare caused by an emergency or malfunction | Yes |
| Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event | No |
| Is this considered a submission for a vent or flare event | Yes, minor venting and/or flaring of natural gas. |
| <i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i> | |
| Was there at least 50 MCF of natural gas vented and/or flared during this event | Yes |
| Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water | No |
| Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence | No |

| | |
|---|---------------|
| Equipment Involved | |
| Primary Equipment Involved | Not answered. |
| Additional details for Equipment Involved. Please specify | Not answered. |

| | |
|--|---------------|
| Representative Compositional Analysis of Vented or Flared Natural Gas <i>Please provide the mole percent for the percentage questions in this group.</i> | |
| Methane (CH4) percentage | 73 |
| Nitrogen (N2) percentage, if greater than one percent | 3 |
| Hydrogen Sulfide (H2S) PPM, rounded up | 0 |
| Carbon Dioxide (CO2) percentage, if greater than one percent | 0 |
| Oxygen (O2) percentage, if greater than one percent | 0 |
| <i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i> | |
| Methane (CH4) percentage quality requirement | Not answered. |
| Nitrogen (N2) percentage quality requirement | Not answered. |
| Hydrogen Sulfide (H2S) PPM quality requirement | Not answered. |
| Carbon Dioxide (CO2) percentage quality requirement | Not answered. |
| Oxygen (O2) percentage quality requirement | Not answered. |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 210537

QUESTIONS (continued)

| | |
|--|--|
| Operator: TARGA MIDSTREAM SERVICES LLC 811 Louisiana Street Houston, TX 77002 | OGRID: 24650 |
| | Action Number: 210537 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

QUESTIONS

| Date(s) and Time(s) | |
|--|------------|
| Date vent or flare was discovered or commenced | 04/21/2023 |
| Time vent or flare was discovered or commenced | 09:30 AM |
| Time vent or flare was terminated | 03:00 PM |
| Cumulative hours during this event | 6 |

| Measured or Estimated Volume of Vented or Flared Natural Gas | |
|---|--|
| Natural Gas Vented (Mcf) Details | Cause: Corrosion Pipeline (Any) Natural Gas Vented Released: 174 Mcf Recovered: 0 Mcf Lost: 174 Mcf. |
| Natural Gas Flared (Mcf) Details | Not answered. |
| Other Released Details | Not answered. |
| Additional details for Measured or Estimated Volume(s). Please specify | Not answered. |
| Is this a gas only submission (i.e. only significant Mcf values reported) | Yes, according to supplied volumes this appears to be a "gas only" report. |

| Venting or Flaring Resulting from Downstream Activity | |
|---|---------------|
| Was this vent or flare a result of downstream activity | No |
| Was notification of downstream activity received by this operator | Not answered. |
| Downstream OGRID that should have notified this operator | Not answered. |
| Date notified of downstream activity requiring this vent or flare | Not answered. |
| Time notified of downstream activity requiring this vent or flare | Not answered. |

| Steps and Actions to Prevent Waste | |
|--|--|
| For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. | True |
| Please explain reason for why this event was beyond this operator's control | Gas was vented to atmosphere when a leak was discovered on Targa's 24" steel pipeline. The leak was due to corrosion. The pipeline is underground, and the corrosion was not visible. The first sign of corrosion on an underground pipeline is a leak. Furthermore, the only want to make repairs is to depressurize the corroded section of pipeline to atmosphere. This event was beyond Targa's control. |
| Steps taken to limit the duration and magnitude of vent or flare | The corroded section of pipeline was isolated and depressurized to atmosphere. Once the section of pipeline was fully depressurized, the emission event ended. |
| Corrective actions taken to eliminate the cause and reoccurrence of vent or flare | The corroded section of pipeline will be replaced. Once it is replaced and verified safe to operate, the pipeline will be returned to normal service. |

District I

1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 210537

ACKNOWLEDGMENTS

| | |
|--|--|
| Operator: TARGA MIDSTREAM SERVICES LLC 811 Louisiana Street Houston, TX 77002 | OGRID: 24650 |
| | Action Number: 210537 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

ACKNOWLEDGMENTS

| | |
|-------------------------------------|---|
| <input checked="" type="checkbox"/> | I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC. |
| <input checked="" type="checkbox"/> | I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively. |
| <input checked="" type="checkbox"/> | I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act. |
| <input checked="" type="checkbox"/> | I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment. |
| <input checked="" type="checkbox"/> | I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations. |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 210537

CONDITIONS

| | |
|--|--|
| Operator: TARGA MIDSTREAM SERVICES LLC 811 Louisiana Street Houston, TX 77002 | OGRID: 24650 |
| | Action Number: 210537 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|--|----------------|
| amberg | If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event. | 4/25/2023 |