

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2313555368
District RP	
Facility ID	fAPP2303735385
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Nathan Sirgo	Contact Telephone: (432) 682-3753
Contact email: nsirgo@btaoil.com	Incident # (assigned by OCD)
Contact mailing address: 104 South Pecos St. Midland, TX 79701	

Location of Release Source

Latitude 32.062833 Longitude -103.652055
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Mesa Dolphin CTB	Site Type:
Date Release Discovered: 4/27/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	11	26S	32E	Lea

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 1,330	Volume Recovered (bbls) 1,326
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

A water line connecting the heater treater and gun barrel ruptured at a seam in the poly line due to vibration. Fluids released to the lined containment and nearby well pad. All freestanding fluids were recovered.

Incident ID	nAPP2313555368
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Release greater than 25 bbls
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Nathan J. Sirgo</u>	Title: <u>Operations Manager</u>
Signature: <u></u>	Date: <u>5/16/2023</u>
email: <u>nsirgo@btaoil.com</u>	Telephone: <u>432-682-3753</u>
<u>OCD Only</u>	
Received by: <u>Jocelyn Harimon</u>	Date: <u>05/26/2023</u>

Location Mesa Dolphin CTB
API #
Spill Date 4/27/2023
Spill Description

Spill Dimensions - Inside Lined Containmentment

ENTER - Length of Spill 275 feet
ENTER - Width of Spill 65 feet
ENTER - Saturation Depth of Spill 5 inches
 Calculated Volume - In Containmentment Only 1326 BBL

Spill Dimensions - Outside Containmentment

ENTER - Length of Spill 60 feet
ENTER - Width of Spill 8 feet
ENTER - Saturation Depth of Spill 0.5 inches
ENTER - Porosity Factor (see chart below) 0 decimal 0.03

Oil Cut - Well Test / Vessel Throughput or Contents

Oil 0
 Water (if leak on water system enter 1) 1
 Calculated Oil Cut 0

Volume Recovered in Truck /100% Recoverable in Lined Containmentment

ENTER - Recovered Oil Outside Containmentment 0 BBL
ENTER - Recovered Water Outside Containmentment 0 BBL

Calculated Values

Release of Oil in Soil - Unrecovered 0.000 BBL 0.000
 Release of Water in Soil - Unrecovered 0.000 BBL 0.107
 Unrecovered Total Release 0.000 BBL 0.107

Calculated Values

Total Release of Oil 0 BBL 0
 Total Release of Water 0 BBL 4
 Total Release 1326 BBL 4

Types of Soil	Porosity Factor
Gravel	0.25
Sand	0.20
Clay/silt/sand Mix	0.15
Clay	0.05
Caliche	0.03

TOTAL SPILL 1330
TOTAL RECOVERY 100%

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 221019

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 221019
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	5/26/2023