

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2327627266
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party DCP Operating Company, LP	OGRID 36785
Contact Name: Nicholas L. Case	Contact Telephone 575-802-5225
Contact email Nicholas.L.Case@p66.com	Incident # (assigned by OCD)
Contact mailing address 5301 Sierra Vista Drive	Carlsbad, NM 88220

Location of Release Source

Latitude 32.695075 Longitude -103.285081
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Linam Ranch	Site Type: Enardo Valve
Date Release Discovered: 9/15/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
A	06	19S	37E	Lea

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: DCP Operating Company, LP)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls):	Volume Recovered (bbls):
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input checked="" type="checkbox"/> Other (describe)	Volume/Weight Released (provide units) NA Due to storms the Enardo Valve was struck by lightning	Volume/Weight Recovered (provide units) NA

Cause of Release:

On October 2, 2023, DCP Ops discovered a fire at Linam Ranch Enardo Valve on the P Tank due to a Lightning strike. The fire was in the incipient stage and was extinguished by operations. There were no injuries, Emergency Services were not notified, there was very little damage (to Enardo Valve), and there are no emissions calculable for this event.

Was this a major release as defined by 19.15.29.7(A) NMAC?

If YES, for what reason(s) does the responsible party consider this a major release?

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Via email to Mike Bratcher on October 2, 2023 at 8:06pm from Nicholas Case with Phillips 66.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Nicholas L. Case Title: Environmental Specialist

Signature: [Signature] Date: 10/04/2023

email: Nicholas.L.Case@p66.com Telephone: 575-802-5225

OCD Only

Received by: Shelly Wells Date: 10/6/2023

Incident ID	nAPP2327627266
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.


Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate OCD District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Nicholas L. Case

Title: Environmental Specialist

Signature: 

10/04/2023

Date:

email: Nicholas.L.Case@p66.com

Telephone: 575-802-5225

OCD Only

Received by: Shelly Wells

Date: 10/6/2023

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Shelly Wells

Date: 10/6/2023

Printed Name: Shelly Wells

Title: Environmental Specialist-Advanced

From: [Case, Nicholas L](#)
To: [Michael Bratcher](#); [Mike Bratcher](#)
Cc: [Cook, John W](#); [Millican, Scot A](#); [Daly, Stacey](#); [Smalts, Raymond A](#); [Acosta, Jonathan](#); [Kyle Norman](#); [Brett Dennis](#); [Brown, Clint](#); [Hargrove, Javier](#); [Case, Nicholas L](#); [Russell, Allen B](#)
Subject: Small incipient fire/ Linam Ranch GP Lea County
Date: Monday, October 2, 2023 8:06:04 PM
Attachments: [image004.png](#)

Mr. Bratcher: I was notified of small fire that occurred around 07:00 pm (10/02/2023) at the LINAM RANCH Gas Plant in Lea County (32.695075 -103.285081). The fire was in the incipient stage and was extinguished by operations. There were no injuries, Emergency Services were not notified, there was very little damage (to an Enardo Valve atop of a tank which was struck by Lightning during this evenings Thunderstorms), and there are no emissions calculable for this event.

Therefore;

In an abundance of caution and to meet potentially applicable reporting deadlines, DCP is submitting this initial report based on the information currently available and DCP's understanding of the facts at this time; however, DCP's investigation and assessment is ongoing. DCP therefore reserves the right to supplement and revise the information in this initial report if and as new information becomes available. DCP also reserves the right to raise any arguments, facts, or defenses regarding this incident, including that this incident is not a "major release" as defined by 19.15.29.7(A) NMAC.

Please contact me if you have any additional questions or concerns for this possible NOR.

Thank you Nick

Nicholas L. Case
Environmental Specialist
SENM Asset

M: 575-802-5225

5301 Sierra Vista Drive | Carlsbad, NM 88220

[phillips66.com](#) Follow us: [Twitter](#) | [Facebook](#) | [LinkedIn](#) | [Instagram](#)





9:25

LTE 

Photo 

Done



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 273136

CONDITIONS

Operator: DCP OPERATING COMPANY, LP 6900 E. Layton Ave Denver, CO 80237	OGRID: 36785
	Action Number: 273136
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	10/6/2023