

FESCO, Ltd.
1100 Fesco Ave. - Alice, Texas 78332

For: Ameredev Operating, LLC
2901 Via Fortuna
Austin, Texas 78746

Sample: Nandina CTB

Sales Meter Run
Spot Gas Sample @ 78 psig & 96°F

Date Sampled: 06/03/2023

Job Number: 232371.005

CHROMATOGRAPH EXTENDED ANALYSIS - GPA 2286

Un-Normalized			
COMPONENT	Mol%	MOL%	GPM
Hydrogen Sulfide*	-----	0.160	
Oxygen	0.001	0.001	
Nitrogen	1.194	1.215	
Carbon Dioxide	0.819	0.834	
Methane	75.340	76.658	
Ethane	10.180	10.358	2.836
Propane	5.697	5.797	1.635
Isobutane	0.927	0.943	0.316
n-Butane	2.006	2.041	0.659
2-2 Dimethylpropane	0.008	0.008	0.003
Isopentane	0.571	0.581	0.218
n-Pentane	0.498	0.506	0.188
Hexanes	0.397	0.411	0.173
Heptanes Plus	<u>0.483</u>	<u>0.487</u>	<u>0.198</u>
Totals	98.121	100.000	6.226

Computed Real Characteristics Of Heptanes Plus:

Specific Gravity ----- 3.303 (Air=1)
Molecular Weight ----- 95.30
Gross Heating Value ----- 5111 BTU/CF

Computed Real Characteristics Of Total Sample:

Specific Gravity ----- 0.765 (Air=1)
Compressibility (Z) ----- 0.9960
Molecular Weight ----- 22.07
Gross Heating Value
Dry Basis ----- 1324 BTU/CF
Saturated Basis ----- 1301 BTU/CF

*Hydrogen Sulfide tested on location by: Stain Tube Method (GPA 2377)
Results: 100.6 Gr/100 CF, 1600 PPMV or 0.160 Mol %

Base Conditions: 15.025 PSI & 60 Deg F

Sampled By: (16) D. Field
Analyst: LG
Processor: HB
Cylinder ID: T 6194

Certified: FESCO, Ltd. - Alice, Texas

Conan Pierce 361-661-7015

CHROMATOGRAPH EXTENDED ANALYSIS - GPA 2286
TOTAL REPORT

COMPONENT	MOL %	GPM	WT %
Hydrogen Sulfide*	0.160		0.247
Oxygen	0.001		0.001
Nitrogen	1.215		1.542
Carbon Dioxide	0.834		1.663
Methane	76.658		55.714
Ethane	10.358	2.836	14.110
Propane	5.797	1.635	11.580
Isobutane	0.943	0.316	2.483
n-Butane	2.041	0.659	5.374
2,2 Dimethylpropane	0.008	0.003	0.026
Isopentane	0.581	0.218	1.899
n-Pentane	0.506	0.188	1.654
2,2 Dimethylbutane	0.007	0.003	0.027
Cyclopentane	0.000	0.000	0.000
2,3 Dimethylbutane	0.046	0.019	0.180
2 Methylpentane	0.130	0.055	0.508
3 Methylpentane	0.081	0.034	0.316
n-Hexane	0.147	0.062	0.574
Methylcyclopentane	0.068	0.025	0.259
Benzene	0.052	0.015	0.184
Cyclohexane	0.069	0.024	0.263
2-Methylhexane	0.018	0.009	0.082
3-Methylhexane	0.022	0.010	0.100
2,2,4 Trimethylpentane	0.012	0.006	0.062
Other C7's	0.043	0.019	0.193
n-Heptane	0.036	0.017	0.163
Methylcyclohexane	0.049	0.020	0.218
Toluene	0.036	0.012	0.150
Other C8's	0.040	0.019	0.200
n-Octane	0.011	0.006	0.057
Ethylbenzene	0.003	0.001	0.014
M & P Xylenes	0.006	0.002	0.029
O-Xylene	0.002	0.001	0.010
Other C9's	0.013	0.007	0.074
n-Nonane	0.002	0.001	0.012
Other C10's	0.004	0.002	0.026
n-Decane	0.001	0.001	0.006
Undecanes (11)	<u>0.000</u>	<u>0.000</u>	<u>0.000</u>
Totals	100.000	6.226	100.000

Computed Real Characteristics of Total Sample

Specific Gravity ----- 0.765 (Air=1)
 Compressibility (Z) ----- 0.9960
 Molecular Weight ----- 22.07

Gross Heating Value

Dry Basis ----- 1324 BTU/CF
 Saturated Basis ----- 1301 BTU/CF

Sample Date: 06/03/2023

Ambient Air Temp: 79 °F

Sample Time: 12:35

Heating Method Utilized: Yes

Analysis Date: 06/10/2023

Sampling Method: Fill & Empty

Analysis Time: 05:44

Device: (GC) S15

Sample Pressure: 78 psig


Make & Model: Shimadzu GC 2014

Sample Temp: 96 °F

Last Verification Date: 06/08/2023

Sampling Flow Rate: 3567 MCF/D

Received by OCD: 2/1/2024 3:51:55 PM Facility #		Date (Flaring Discovered)	Date Flaring Occurred	Location	Flare Source Equipment	Gas Volume (MCF)	Flared or Vented	Start Time of the flare event	End Time of the flare event	Flare Duration (hr)	C129 Filing Reason	Page 3 of 9
NA	NA	1/18/2024	1/1/2024	Red Bud	VRU Discharge	74.05	Flared	12:00 AM	11:21 AM	7.17	Oxygen	Facility was getting O2 spikes from the tank
FAPP2203927141	1/19/2024	1/18/2024	1/5/2024	Red Bud	LP - Vent flare/Blower Flare	104.68	Flared	12:01 AM	11:56 PM	14.70	Flared more than 8 HRs	Sales blowers were switched off due to high
FAPP2203855966		1/22/2024	1/10/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	88.04	Flared	12:01 AM	6:52 PM	15.88	Flared more than 8 HRs	Contact Tower ACI VRUs were having volta
FAPP2203855966		1/22/2024	1/11/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	128.26	Flared	1:56 PM	5:47 PM	2.37	Malfunction	Contact Tower ACI VRUs were having volta
FAPP2203855966		1/22/2024	1/12/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	324.20	Flared	10:08 AM	5:15 PM	6.28	Malfunction	Contact Tower ACI VRUs were having volta
FAPP2203855966		1/22/2024	1/14/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	365.25	Flared	8:17 AM	10:03 PM	5.68	Malfunction	Contact Tower ACI VRUs were having volta
FAPP2203855966		1/22/2024	1/15/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	282.11	Flared	10:19 AM	5:59 PM	4.60	Malfunction	Contact Tower ACI VRUs were having volta
FAPP2203855966	1/17/2024	1/17/2024	1/16/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	520.34	Flared	8:38 AM	7:00 PM	7.43	Malfunction	Contact Tower ACI VRUs were having volta
FAPP2203855966	1/18/2024	1/18/2024	1/17/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	635.06	Flared	5:47 AM	8:27 PM	10.42	Flared more than 8 HRs	Contact Tower ACI VRUs were having volta
FAPP2203856979		1/22/2024	1/17/2024	Nandina	LP Flare Estimation Sheet - Tank Pressure, Valve Status	77.81	Flared	9:04 AM	10:06 PM	3.23	Malfunction	Control Room opened up production and V
FAPP2203855966		1/22/2024	1/18/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	428.17	Flared	7:24 AM	4:39 PM	8.72	Flared more than 8 HRs	Contact Tower ACI VRUs were having volta
NA	NA	1/19/2024	1/18/2024	Nandina	HP Flare	119.69	Flared	12:36 AM	11:12 PM	5.62	Oxygen	Control Room has been purging the vessels
FAPP2203856979	1/19/2024	1/19/2024	1/18/2024	Nandina	VRU Discharge	621.06	Flared	12:01 AM	11:53 PM	23.99	Flared more than 8 HRs	Control Room has been purging the vessels
FAPP2203855966		1/22/2024	1/19/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	68.43	Flared	8:06 AM	9:12 AM	1.02	Malfunction	Contact Tower ACI VRUs were having volta
FAPP2203856979		1/22/2024	1/19/2024	Nandina	HP Flare	271.06	Flared	12:12 AM	11:23 PM	12.31	Flared more than 8 HRs	Control Room has been purging the vessels
FAPP2203856979		1/22/2024	1/19/2024	Nandina	VRU Discharge	315.22	Flared	12:00 PM	11:59 PM	24.00	Flared more than 8 HRs	Control Room has been purging the vessels
FAPP2304126884		1/22/2024	1/19/2024	Nan 1.5N	HP Flare	92.73	Flared	1:32 AM	6:39 PM	0.19	Malfunction	ETC was having issues, causing line pressur
FAPP2203855966		1/22/2024	1/20/2024	Firethorn	LP Flare Estimation Sheet - Contact Tower	114.57	Flared	8:14 AM	10:10 AM	1.95	Malfunction	ACI VRUs faulted on low discharge over nig
FAPP2203856979		1/22/2024	1/20/2024	Nandina	HP Flare	209.25	Flared	12:23 AM	1:17 PM	11.24	Flared more than 8 HRs	Control Room has been purging the vessels
FAPP2203856980		1/22/2024	1/20/2024	Nandina	VRU Discharge	449.65	Flared	12:00 AM	11:05 PM	22.40	Flared more than 8 HRs	Control Room has been purging the vessels
FAPP2203856981		1/22/2024	1/21/2024	Nandina	HP Flare	139.69	Flared	9:12 AM	11:51 PM	11.90	Flared more than 8 HRs	Separators are being purged for high O2.
FAPP2203856982	1/22/2024	1/22/2024	1/21/2024	Nandina	VRU Discharge	607.41	Flared	12:00 AM	11:48 PM	23.99	Flared more than 8 HRs	Facility is purging O2 since vessels are bein
FAPP2203856983		1/23/2024	1/22/2024	Nandina	HP Flare	192.38	Flared	12:51 AM	7:58 PM	10.85	Flared more than 8 HRs	Separators are being purged for high O2.
FAPP2203856984		1/23/2024	1/22/2024	Nandina	VRU Discharge	451.98	Flared	12:00 AM	6:27 PM	17.47	Flared more than 8 HRs	Facility is purging O2 since vessels are bein
NA	NA	1/23/2024	1/22/2024	Red Bud	VRU Discharge	87.38	Flared	10:07 AM	11:39 AM	3.32	Oxygen	Sales blowers were turned on which cause



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 310589

DEFINITIONS

Operator: AMEREDEV OPERATING, LLC 2901 Via Fortuna Austin, TX 78746	OGRID: 372224
	Action Number: 310589
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.
--

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 310589

QUESTIONS

Operator: AMEREDEV OPERATING, LLC 2901 Via Fortuna Austin, TX 78746	OGRID: 372224
	Action Number: 310589
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.	
Incident Well	Unavailable.
Incident Facility	[fAPP2203856979] NANDINA

Determination of Reporting Requirements Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.	
Was this vent or flare caused by an emergency or malfunction	No
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas Please provide the mole percent for the percentage questions in this group.	
Methane (CH4) percentage	77
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (C02) percentage, if greater than one percent	1
Oxygen (02) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (C02) percentage quality requirement	Not answered.
Oxygen (02) percentage quality requirement	Not answered.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 310589

QUESTIONS (continued)

Operator: AMEREDEV OPERATING, LLC 2901 Via Fortuna Austin, TX 78746	OGRID: 372224
	Action Number: 310589
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	01/21/2024
Time vent or flare was discovered or commenced	09:12 AM
Time vent or flare was terminated	11:51 PM
Cumulative hours during this event	12

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Commissioning to Purge Flow Line - Production Natural Gas Flared Released: 140 Mcf Recovered: 0 Mcf Lost: 140 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	Separators are being purged for high O2.
Steps taken to limit the duration and magnitude of vent or flare	We choked back the wells to limit production.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	We have a designated personnel just to deal with oxygen issue now, hoping to minimize any flare resulting from oxygen spike.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 310589

ACKNOWLEDGMENTS

Operator: AMEREDEV OPERATING, LLC 2901 Via Fortuna Austin, TX 78746	OGRID: 372224
	Action Number: 310589
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 310589

CONDITIONS

Operator: AMEREDEV OPERATING, LLC 2901 Via Fortuna Austin, TX 78746	OGRID: 372224
	Action Number: 310589
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
cscayu	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	2/1/2024