District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party				OGRID	OGRID		
Contact Name				Contact T	Contact Telephone		
Contact email I				Incident #	Incident # (assigned by OCD)		
Contact mail	ing address						
			Location	of Release S	ource		
Latitude			(NAD 83 in dec	Longitude imal degrees to 5 decir	mal places)		
Site Name				Site Type			
Date Release	Discovered			API# (if app	plicable)		
Unit Letter	Section	Township	Range	Cour	nty		
Crude Oil	Material	Federal Tr	Nature and	Volume of	justification for t	he volumes provided below) covered (bbls)	
Produced		Volume Release			Volume Recovered (bbls)		
Is the concentration of dissolved chlorid produced water >10,000 mg/l?			nloride in the		No		
Condensa	te	Volume Released	d (bbls)		Volume Recovered (bbls)		
☐ Natural Gas Volume Released (Mcf)				Volume Rec	covered (Mcf)		
Other (describe) Volume/Weight Released (provide units)			units)	Volume/We	ight Recovered (provide units)		
Cause of Rela	ease						

Received by OCD: 4/8/2024 1:41:04 PM Form C-141 State of New Mexico Page 2 Oil Conservation Division

	rage 2 0j
Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible	le party consider this a major release?
☐ Yes ☐ No		
If YES, was immediate no	otice given to the OCD? By whom? To whom	? When and by what means (phone, email, etc)?
	Initial Resp	oonse
The responsible	party must undertake the following actions immediately unl	ess they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.	
☐ The impacted area ha	as been secured to protect human health and the	environment.
Released materials ha	ave been contained via the use of berms or dike	s, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed and ma	anaged appropriately.
has begun, please attach	a narrative of actions to date. If remedial effo	diation immediately after discovery of a release. If remediation rts have been successfully completed or if the release occurred se attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release notificat ment. The acceptance of a C-141 report by the OCD gate and remediate contamination that pose a threat to	of my knowledge and understand that pursuant to OCD rules and ions and perform corrective actions for releases which may endanger does not relieve the operator of liability should their operations have groundwater, surface water, human health or the environment. In onsibility for compliance with any other federal, state, or local laws
Printed Name		Title:
Signature:	tangsparge	Date:
email:	T	elephone:
OCD Only		
Received by:	Da	ate:

8		S	Y		Jpiii Cuicu	iddoir - Oil-i dd	Juriuce Foor Jpin
Received by OCD: 4/8/202 Convert irregular shape into a series of rectangles	24 1:41: Length (ft.)	04 PM Width (ft.)	Average Depth (in.)	Estimated <u>Pool</u> Area (sq. ft.)	Estimated volume of each pool area (bbl.)	Penetration allowance (ft.)	Total Estimate ชื่อเลย เก็บ อาการ์ อ
Rectangle A	58	5	1.5	290.00	6.45	0.01	6.49
Rectangle B	15	28	1.0	420.00	6.23	0.00	6.26
Rectangle C				0.00	0.00	0.00	0.00
Rectangle D				0.00	0.00	0.00	0.00
Rectangle E				0.00	0.00	0.00	0.00
Rectangle F				0.00	0.00	0.00	0.00
Rectangle G				0.00	0.00	0.00	0.00
Rectangle H		ï		0.00	0.00	0.00	0.00
Rectangle I		i ii		0.00	0.00	0.00	0.00
Released to Imaging: 4/8/	2024 3:4	13:37 P	И	0.00	0.00	0.00	0.00
			Total Surfa	ace Pool Volume	Released, Release	to Soil/Caliche:	12.7488

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 331071

QUESTIONS

ı	Operator:	OGRID:
ı	COG PRODUCTION, LLC	217955
ı	600 W. Illinois Ave	Action Number:
ı	Midland, TX 79701	331071
ı		Action Type:
ı		[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2409948979	
Incident Name	NAPP2409948979 WINDWARD WEST CTB @ 0	
Incident Type	Produced Water Release	
Incident Status	Initial C-141 Received	
Incident Facility	[fDHR1921042438] WINDWARD WEST CTB	

Location of Release Source		
Please answer all the questions in this group.		
Site Name Windward West CTB		
Date Release Discovered	04/01/2024	
Surface Owner	Federal	

Incident Details			
Please answer all the questions in this group.	Please answer all the questions in this group.		
Incident Type	Produced Water Release		
Did this release result in a fire or is the result of a fire	No		
Did this release result in any injuries	No		
Has this release reached or does it have a reasonable probability of reaching a watercourse	No		
Has this release endangered or does it have a reasonable probability of endangering public health	No		
Has this release substantially damaged or will it substantially damage property or the environment	No		
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No		

Nature and Volume of Release				
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.				
Crude Oil Released (bbls) Details	Not answered.			
Produced Water Released (bbls) Details	Cause: Corrosion Flow Line - Production Produced Water Released: 13 BBL Recovered: 10 BBL Lost: 3 BBL.			
Is the concentration of chloride in the produced water >10,000 mg/l	Yes			
Condensate Released (bbls) Details	Not answered.			
Natural Gas Vented (Mcf) Details	Not answered.			
Natural Gas Flared (Mcf) Details	Not answered.			
Other Released Details	Not answered.			
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Not answered.			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 331071

Phone: (505) 476-3470 Fax: (505) 476-3462	,
QUESTI	ONS (continued)
Operator: COG PRODUCTION, LLC 600 W. Illinois Ave Midland, TX 79701	OGRID:
QUESTIONS	[5]
Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	No
Reasons why this would be considered a submission for a notification of a major release	Unavailable.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e.	e. gas only) are to be submitted on the C-129 form.
Initial Response	
The responsible party must undertake the following actions immediately unless they could create a s	afety hazard that would result in injury.
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.
	ation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of valuation in the follow-up C-141 submission.
to report and/or file certain release notifications and perform corrective actions for releating the OCD does not relieve the operator of liability should their operations have failed to a	knowledge and understand that pursuant to OCD rules and regulations all operators are required ases which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface t does not relieve the operator of responsibility for compliance with any other federal, state, or
I hereby agree and sign off to the above statement	Name: Brittany Esparza Title: Environmental Technician Email: brittany Esparza@ConocoPhillips.com

Date: 04/08/2024

District I

QUESTIONS

A 100-year floodplain

storage site

Did the release impact areas not on an exploration, development, production, or

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

Phone: (575) 748-1283 Fax: (575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 3

Action 331071

QUESTIONS (continued)

Operator:	OGRID:
COG PRODUCTION, LLC	217955
600 W. Illinois Ave Midland, TX 79701	Action Number: 331071
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

Site Characterization Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the elease discovery date. What is the shallowest depth to groundwater beneath the area affected by the Not answered. release in feet below ground surface (ft bgs) What method was used to determine the depth to ground water Not answered. Did this release impact groundwater or surface water Not answered. What is the minimum distance, between the closest lateral extents of the release and the following surface areas: A continuously flowing watercourse or any other significant watercourse Not answered. Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) Not answered. An occupied permanent residence, school, hospital, institution, or church Not answered. A spring or a private domestic fresh water well used by less than five households Not answered for domestic or stock watering purposes Any other fresh water well or spring Not answered. Incorporated municipal boundaries or a defined municipal fresh water well field Not answered. A wetland Not answered. A subsurface mine Not answered. An (non-karst) unstable area Not answered. Categorize the risk of this well / site being in a karst geology Not answered.

Remediation Plan		
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.		
Requesting a remediation plan approval with this submission	No	
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.		

Not answered.

Not answered.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 331071

CONDITIONS

Operator:	OGRID:
COG PRODUCTION, LLC	217955
600 W. Illinois Ave	Action Number:
Midland, TX 79701	331071
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By	Condition	Condition Date
scott.rodgers	None	4/8/2024