

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

QUESTIONS

Action 362896

QUESTIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 362896
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2418357364
Incident Name	NAPP2418357364 ROJO 14H-17H 26-29H BATTERY RELEASE @ 0
Incident Type	Produced Water Release
Incident Status	Notification Accepted
Incident Facility	[fAPP2130123218] Rojo 14 - 17

Location of Release Source	
Site Name	Rojo 14H-17H 26-29H Battery Release
Date Release Discovered	06/30/2024
Surface Owner	Private

Liner Inspection Event Information	
Please answer all the questions in this group.	
What is the liner inspection surface area in square feet	7,400
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	07/10/2024
Time liner inspection will commence	03:00 PM
Warning: Notification can not be less than two business days prior to conducting liner inspection.	
Please provide any information necessary for observers to liner inspection	Please contact Chuck Terhune of tetra Tech at chuck.terhune@tetratech.com or 831-252-2093 to coordinate with on-site inspection.
Please provide any information necessary for navigation to liner inspection site	From the intersection of Highway 128 and Medera Road, head south on Medara Road for 0.3 miles, then head west on Battle Axe Road. Continue on battle Axe Road for 10.45 miles, then head northwest on Dimond Road for 3.65 miles, then head south on the elase road for .92 miles, then head west past the frac pond and you have arrived at the site located at 32.11084, -103.555872

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 362896

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 362896
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
cterhune	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	7/10/2024