Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 405427

## **QUESTIONS**

ı	Operator:	OGRID:
ı	APACHE CORPORATION	873
ı	303 Veterans Airpark Ln	Action Number:
ı	Midland, TX 79705	405427
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

## QUESTIONS

Prerequisites	es e	
Incident ID (n#)	nLWJ0520029619	
Incident Name	NLWJ0520029619 2005 MAJOR A SWS @ 0	
Incident Type	Produced Water Release	
Incident Status	Closure Not Approved	

Location of Release Source		
Site Name	Unavailable.	
Date Release Discovered	07/15/2005	
Surface Owner	State	

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	2,089			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	11/25/2024			
Time liner inspection will commence	09:00 AM			
Please provide any information necessary for observers to liner inspection	JOE- 575-441-2661			
Please provide any information necessary for navigation to liner inspection site	GPS: 32.430072 -103.117093			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 405427

## **CONDITIONS**

Operator:	OGRID:
APACHE CORPORATION	873
303 Veterans Airpark Ln	Action Number:
Midland, TX 79705	405427
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

## CONDITIONS

Created By	Condition	Condition Date
Ibaker	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	11/21/2024