

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 412698

**QUESTIONS**

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 412698
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

**QUESTIONS**

Prerequisites	
Incident ID (n#)	nAPP2432332325
Incident Name	NAPP2432332325 COTTON DRAW 32 STATE SWD #002 @ 30-025-41524
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved
Incident Well	[30-025-41524] COTTON DRAW 32 STATE SWD #002

Location of Release Source	
Site Name	COTTON DRAW 32 STATE SWD #002
Date Release Discovered	11/17/2024
Surface Owner	State

Liner Inspection Event Information	
<i>Please answer all the questions in this group.</i>	
What is the liner inspection surface area in square feet	9,850
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	12/19/2024
Time liner inspection will commence	10:00 AM
Please provide any information necessary for observers to liner inspection	Monica Peppin 575.909.3418 <a href="mailto:monica.peppin@soudermiller.com">monica.peppin@soudermiller.com</a>
Please provide any information necessary for navigation to liner inspection site	Intersection 128/C1 follow C1 south for 2.4 miles, turn left onto lease road travel west for 1 mile, turn left south travel 0.52 miles, follow turn to the right/west 0.10 miles, slight turn back south across site south for 0.11 miles, travel south for 0.15 miles and end on site 32.169583, -103.691730

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 412698

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 412698
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
jralej	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	12/17/2024