Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 419487

QUESTIONS

ı	Operator:	OGRID:
ı	CAZA OPERATING, LLC	249099
ı	200 N Loraine St	Action Number:
ı	Midland, TX 79701	419487
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

equisites	
Incident ID (n#)	nAPP2231454863
Incident Name	NAPP2231454863 ALISA OGDEN CTB @ 30-015-45234
Incident Type	Fire
Incident Status	Initial C-141 Approved
Incident Well	[30-015-45234] ALISA OGDEN 15 #002H

Location of Release Source		
Site Name	ALISA OGDEN CTB	
Date Release Discovered	09/05/2022	
Surface Owner	Private	

Liner Inspection Event Information					
lease answer all the questions in this group.					
What is the liner inspection surface area in square feet	23,000				
Have all the impacted materials been removed from the liner	Yes				
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	01/14/2025				
Time liner inspection will commence	08:30 AM				
Please provide any information necessary for observers to liner inspection	NTGE - (580) 682-1889				
Please provide any information necessary for navigation to liner inspection site	32.30221,-104.170331				

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 419487

CONDITIONS

Operator:	OGRID:
CAZA OPERATING, LLC	249099
200 N Loraine St	Action Number:
Midland, TX 79701	419487
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By		Condition Date
karrendondo	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	1/10/2025