



Certificate of Analysis

Number: 6030-24100397-004A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Jose Rosales
Marlin Operating, LLC
1371 Brumlow Ave
Suite A
Southlake, TX 76092

Station Name: Pegasus CTB Scanner 2000
Station Number: Peg CTB Scanner
Station Location: Marlin OP
Sample Point: Meter Run
Method: GPA-2261M
Cylinder No: 1111-007267
Instrument: 6030_GC6 (Inficon GC-3000 Micro)
Last Inst. Cal.: 10/14/2024 08:20:42
Analyzed: 10/14/2024 12:08:29 by EBH

Report Date: 10/14/2024
Sampled By: Raul Salazar
Sample Of: Gas Spot
Sample Date: 10/10/2024 11:20
Sample Conditions: 180.54 psig, @ 90.5 °F Ambient: 80 °F
Received Date: 10/11/2024
Login Date: 10/11/2024
Effective Date: 10/10/2024 11:20
Flow Rate: 154 MSCFD

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.73 psia		
Hydrogen Sulfide	0.0000	0.3000	0.4544		GPM TOTAL C2+	4.232
Nitrogen	2.1616	2.1300	2.6518		GPM TOTAL C3+	2.062
Methane	75.0734	73.9755	52.7416		GPM TOTAL iC5+	0.459
Carbon Dioxide	8.9522	8.8213	17.2533			
Ethane	8.2067	8.0867	10.8065	2.170		
Propane	3.7371	3.6825	7.2166	1.018		
Iso-butane	0.5523	0.5442	1.4057	0.179		
n-Butane	1.3026	1.2836	3.3156	0.406		
Iso-pentane	0.4120	0.4060	1.3018	0.149		
n-Pentane	0.3659	0.3605	1.1559	0.131		
Hexanes Plus	0.4158	0.4097	1.6968	0.179		
	101.1796	100.0000	100.0000	4.232		

Calculated Physical Properties

Relative Density Real Gas	Total	C6+
	0.7793	3.2176
Calculated Molecular Weight	22.50	93.19
Compressibility Factor	0.9965	

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.73 psia & 60°F

Real Gas Dry BTU	1102.5	5141.1
Water Sat. Gas Base BTU	1083.7	5051.6
Ideal, Gross HV - Dry at 14.73 psia	1098.6	5141.1
Ideal, Gross HV - Wet	1079.5	5051.6

Comments: H2S Field Content: 3000 ppm

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated. The test results apply to the sample as received.

C-129

January 10, 2025 Measured Volume

Gas Flared
MCF
Flare Reported
55.46

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 415797

DEFINITIONS

Operator: Marlin Operating, LLC 1371 Brumlow Avenue Southlake, TX 76092	OGRID: 331054
	Action Number: 415797
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 415797

QUESTIONS

Operator: Marlin Operating, LLC 1371 Brumlow Avenue Southlake, TX 76092	OGRID: 331054
	Action Number: 415797
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	Unavailable.
Incident Facility	[fAPP2309032089] Pegasus CTB

Determination of Reporting Requirements <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	No
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas <i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	77
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	3
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 415797

QUESTIONS (continued)

Operator: Marlin Operating, LLC 1371 Brumlow Avenue Southlake, TX 76092	OGRID: 331054
	Action Number: 415797
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	01/10/2025
Time vent or flare was discovered or commenced	02:00 AM
Time vent or flare was terminated	03:00 AM
Cumulative hours during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Well Natural Gas Flared Released: 55 Mcf Recovered: 0 Mcf Lost: 55 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	Yes
Was notification of downstream activity received by this operator	No
Downstream OGRID that should have notified this operator	[331548] Targa Northern Delaware, LLC.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	Midstream highline pressure
Steps taken to limit the duration and magnitude of vent or flare	Compression onsite
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Compressor onsite

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 415797

ACKNOWLEDGMENTS

Operator: Marlin Operating, LLC 1371 Brumlow Avenue Southlake, TX 76092	OGRID: 331054
	Action Number: 415797
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 415797

CONDITIONS

Operator: Marlin Operating, LLC 1371 Brumlow Avenue Southlake, TX 76092	OGRID: 331054
	Action Number: 415797
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
kathy short	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	1/13/2025