

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oecd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 422663

**QUESTIONS**

|                                                                                  |                                                            |
|----------------------------------------------------------------------------------|------------------------------------------------------------|
| Operator:<br>TAP ROCK OPERATING, LLC<br>523 Park Point Drive<br>Golden, CO 80401 | OGRID:<br>372043                                           |
|                                                                                  | Action Number:<br>422663                                   |
|                                                                                  | Action Type:<br>[NOTIFY] Notification Of Sampling (C-141N) |

**QUESTIONS**

| Prerequisites     |                                     |
|-------------------|-------------------------------------|
| Incident ID (n#)  | nAPP2436138858                      |
| Incident Name     | NAPP2436138858 PROMETHEUS A CTB @ 0 |
| Incident Type     | Produced Water Release              |
| Incident Status   | Initial C-141 Approved              |
| Incident Facility | [fAPP2212541268] Prometheus A CTB   |

| Location of Release Source |                  |
|----------------------------|------------------|
| Site Name                  | Prometheus A CTB |
| Date Release Discovered    | 12/25/2024       |
| Surface Owner              | State            |

| Sampling Event General Information                                                              |                        |
|-------------------------------------------------------------------------------------------------|------------------------|
| <i>Please answer all the questions in this group.</i>                                           |                        |
| What is the sampling surface area in square feet                                                | 15,900                 |
| What is the estimated number of samples that will be gathered                                   | 90                     |
| Sampling date pursuant to Subparagraph (a) of Paragraph (1) of Subsection D of 19.15.29.12 NMAC | 01/28/2025             |
| Time sampling will commence                                                                     | 08:00 AM               |
| Please provide any information necessary for observers to contact samplers                      | Vertex. 575-263-3295   |
| Please provide any information necessary for navigation to sampling site                        | 32.200787, -103.566924 |

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 422663

CONDITIONS

|                                                                                  |                                                            |
|----------------------------------------------------------------------------------|------------------------------------------------------------|
| Operator:<br>TAP ROCK OPERATING, LLC<br>523 Park Point Drive<br>Golden, CO 80401 | OGRID:<br>372043                                           |
|                                                                                  | Action Number:<br>422663                                   |
|                                                                                  | Action Type:<br>[NOTIFY] Notification Of Sampling (C-141N) |

CONDITIONS

| Created By | Condition                                                                                                                                                                                             | Condition Date |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| vertex1    | Failure to notify the OCD of sampling events including any changes in date/time per the requirements of 19.15.29.12.D.(1).(a) NMAC, may result in the remediation closure samples not being accepted. | 1/21/2025      |