Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 425744

QUESTIONS

Operator:	OGRID:
CIMAREX ENERGY CO.	215099
6001 Deauville Blvd	Action Number:
Midland, TX 79706	425744
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2434729375	
Incident Name	NAPP2434729375 IRWIN 13 FEDERAL @ 0	
Incident Type	Produced Water Release	
Incident Status	Initial C-141 Approved	
Incident Facility	[fAPP2202782856] IRWIN 13 FEDERAL	

Location of Release Source		
Site Name	IRWIN 13 FEDERAL	
Date Release Discovered	12/11/2024	
Surface Owner	Federal	

Liner Inspection Event Information			
Please answer all the questions in this group.			
What is the liner inspection surface area in square feet	485		
Have all the impacted materials been removed from the liner	Yes		
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	01/30/2025		
Time liner inspection will commence	08:00 AM		
Please provide any information necessary for observers to liner inspection	na		
Please provide any information necessary for navigation to liner inspection site	na		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 425744

CONDITIONS

Operator:	OGRID:
CIMAREX ENERGY CO.	215099
6001 Deauville Blvd	Action Number:
Midland, TX 79706	425744
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
nrose	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	1/28/2025