Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 428295

QUESTIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	428295
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2418556332	
Incident Name	NAPP2418556332 PRONGHORN SWD #1 @ 30-025-32735	
Incident Type	Produced Water Release	
Incident Status	Initial C-141 Approved	
Incident Well	[30-025-32735] PRONGHORN SWD #001	

Location of Release Source		
Site Name	PRONGHORN SWD #1	
Date Release Discovered	07/02/2024	
Surface Owner	Federal	

Liner Inspection Event Information		
ease answer all the questions in this group.		
What is the liner inspection surface area in square feet	13,125	
Have all the impacted materials been removed from the liner	Yes	
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	02/07/2025	
Time liner inspection will commence	08:00 AM	
Please provide any information necessary for observers to liner inspection	Angel Pena	
Please provide any information necessary for navigation to liner inspection site	32.6521051,-103.7164501	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 428295

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway Houston, TX 77024	Action Number: 428295
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By		Condition Date
apena	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	2/4/2025