Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 434762

## **QUESTIONS**

| ı | Operator:            | OGRID:   |
|---|----------------------|--|
| ı | DJR OPERATING, LLC   | 371838   |
| ı | 200 Energy Court     | Action Number:                                     |
| ı | Farmington, NM 87401 | 434762   |
| ı |                      | Action Type:                                       |
| ı |                      | [NOTIFY] Notification Of Liner Inspection (C-141L) |

## QUESTIONS

| requisites       |   |
|------------------|---|
| Incident ID (n#) | nAPP2500652515                                  |
| Incident Name    | NAPP2500652515 NAGEEZI UNIT 314H @ 30-045-38195 |
| Incident Type    | Produced Water Release                          |
| Incident Status  | Initial C-141 Approved                          |
| Incident Well    | [30-045-38195] NAGEEZI UNIT #314H               |

| Location of Release Source |                   |  |
|----------------------------|-------------------|--|
| Site Name                  | NAGEEZI UNIT 314H |  |
| Date Release Discovered    | 01/02/2025        |  |
| Surface Owner              | Federal           |  |

| Liner Inspection Event Information  |  |  |  |
|---|--|--|--|
| e answer all the questions in this group.   |  |  |  |
| What is the liner inspection surface area in square feet  | 4,250  |  |  |
| Have all the impacted materials been removed from the liner   | Yes  |  |  |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 02/26/2025   |  |  |
| Time liner inspection will commence   | 12:00 PM   |  |  |
| Please provide any information necessary for observers to liner inspection                              | Bill Lowman will be contact onsite 505-320-0070  |  |  |
| Please provide any information necessary for navigation to liner inspection site                        | FROM THE INTERSECTION OF HWY 64 & HWY 550 IN BLOOMFIELD, GO SOUTH ON HWY 550, 36.8 MILES TO C.R. 7800. TURN RIGHT ON C.R. 7800 AND GO 2.4 MILES TO FLAGGED ACCESS ON LEFT SIDE OF ROAD |  |  |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 434762

## **CONDITIONS**

| Operator:            | OGRID:   |
|----------------------|--|
| DJR OPERATING, LLC   | 371838   |
| 200 Energy Court     | Action Number:                                     |
| Farmington, NM 87401 | 434762   |
|                      | Action Type:                                       |
|                      | [NOTIFY] Notification Of Liner Inspection (C-141L) |

## CONDITIONS

| Created By  |  | Condition<br>Date |
|-------------|--|-------------------|
| hhuntington | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 2/24/2025         |