

***** LIQUID SPILLS - VOLUME CALCULATIONS *****

Location of spill: Comanche 25-36 Fed State Com 1H-4H Production Facility

Date of Spill: 4-Mar-2025

If the leak/spill is associated with production equipment, i.e. - wellhead, stuffing box, flowline, tank battery, production vessel, transfer pump, or storage tank place an "X" here:

X

Input Data:

OIL: 8.0 BBL

WATER: 0.0 BBL

If spill volumes from measurement, i.e. metering, tank volumes, etc. are known enter the volumes here:

If "known" spill volumes are given, input data for the following "Area Calculations" is optional. The above will override the calculated volumes.

Total Area Calculations

Total Surface Area	width	length	wet soil depth	oil (%)
Rectangle Area #1	50 ft	75 ft	X 1.00 in	0%
Rectangle Area #2	0 ft	0 ft	X 0 in	0%
Rectangle Area #3	0 ft	0 ft	X 0 in	0%
Rectangle Area #4	0 ft	0 ft	X 0 in	0%
Rectangle Area #5	0 ft	0 ft	X 0 in	0%
Rectangle Area #6	0 ft	0 ft	X 0 in	0%
Rectangle Area #7	0 ft	0 ft	X 0 in	0%
Rectangle Area #8	0 ft	0 ft	X 0 in	0%

Standing Liquid Calculations

Standing Liquid Area	width	length	liquid depth	oil (%)
Rectangle Area #1	0 ft	0 ft	X 0 in	0%
Rectangle Area #2	0 ft	0 ft	X 0 in	0%
Rectangle Area #3	0 ft	0 ft	X 0 in	0%
Rectangle Area #4	0 ft	0 ft	X 0 in	0%
Rectangle Area #5	0 ft	0 ft	X 0 in	0%
Rectangle Area #6	0 ft	0 ft	X 0 in	0%
Rectangle Area #7	0 ft	0 ft	X 0 in	0%
Rectangle Area #8	0 ft	0 ft	X 0 in	0%

okay

production system leak - DAILY PRODUCTION DATA REQUIRED

Average Daily Production: Oil 0 BBL Water 0 BBL 0 Gas (MCFD)

Did leak occur before the separator?: YES N/A (place an "X")

Amount of Free Liquid Recovered: 0 BBL okay

Liquid holding factor *: 0.14 gal per gal

Total Hydrocarbon Content in gas: 0% (percentage)

H2S Content in Produced Gas: 0 PPM

H2S Content in Tank Vapors: 0 PPM

Percentage of Oil in Free Liquid Recovered: 0% (percentage)

Use the following when the spill wets the grains of the soil.

Use the following when the liquid completely fills the pore space of the soil:

* Sand = 0.08 gallon (gal.) liquid per gal. volume of soil.

Occurs when the spill soaked soil is contained by barriers, natural (or not).

* Gravelly (caliche) loam = 0.14 gal. liquid per gal. volume of soil.

* Clay loam = 0.16 gal. liquid per gal. volume of soil.

* Gravelly (caliche) loam = 0.25 gal. liquid per gal. volume of soil.

* Sandy loam = 0.5 gal. liquid per gal. volume of soil.

Total Solid/Liquid Volume: 3,750 sq. ft. 313 cu. ft. cu. ft.

Total Free Liquid Volume: sq. ft. cu. ft. cu. ft.

Estimated Volumes Spilled

	H2O	OIL
Liquid in Soil:	7.8 BBL	0.0 BBL
Free Liquid:	0.0 BBL	0.0 BBL
Totals:	7.8 BBL	0.0 BBL

Total Liquid Spill Liquid: 7.8 BBL 8.00 BBL

Estimated Production Volumes Lost

	H2O	OIL
Estimated Production Spilled:	0.0 BBL	8.0 BBL

Estimated Surface Damage

Surface Area: 3,750 sq. ft. .0861 acre

Estimated Weights, and Volumes

Saturated Soil =	35,000 lbs	313 cu. ft.	12 cu. yds.
Total Liquid =	16 BBL	663 gallon	5,518 lbs

Recovered Volumes

Estimated oil recovered: BBL check - okay

Estimated water recovered: BBL check - okay

Air Emission from flowline leaks:

Volume of oil spill: - BBL

Separator gas calculated: - MCF

Separator gas released: - MCF

Gas released from oil: - lb

H2S released: - lb

Total HC gas released: - lb

Total HC gas released: - MCF

Air Emission of Reporting Requirements:

New Mexico

Texas

HC gas release reportable? NO NO

H2S release reportable? NO NO

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 439778

QUESTIONS

Operator: CAZA OPERATING, LLC 200 N Loraine St Midland, TX 79701	OGRID: 249099
	Action Number: 439778
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2506358344
Incident Name	NAPP2506358344 COMANCHE 25-36 FED STATE COM 1H-4H PRODUCTION FACI @ 0
Incident Type	Oil Release
Incident Status	Initial C-141 Received
Incident Facility	[fAPP2429045580] Comanche 25-36 Fed State Com 1H-4H Production Faci

Location of Release Source

Please answer all the questions in this group.

Site Name	Comanche 25-36 Fed State Com 1H-4H Production Faci
Date Release Discovered	03/04/2025
Surface Owner	Federal

Incident Details

Please answer all the questions in this group.

Incident Type	Oil Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release

Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.

Crude Oil Released (bbls) Details	Cause: Equipment Failure Other (Specify) Crude Oil Released: 8 BBL Recovered: 0 BBL Lost: 8 BBL.
Produced Water Released (bbls) Details	Not answered.
Is the concentration of chloride in the produced water >10,000 mg/l	No
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Flare Spray

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 439778

QUESTIONS (continued)

Operator: CAZA OPERATING, LLC 200 N Loraine St Midland, TX 79701	OGRID: 249099
	Action Number: 439778
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	No
Reasons why this would be considered a submission for a notification of a major release	Unavailable.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.

The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.

Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Kelly Arrendondo Title: Production Reporting Manager Email: karredondo@ntglobal.com Date: 03/06/2025
--	---

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 3

Action 439778

QUESTIONS (continued)

Operator: CAZA OPERATING, LLC 200 N Loraine St Midland, TX 79701	OGRID: 249099
	Action Number: 439778
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Site Characterization	
<i>Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.</i>	
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Not answered.
What method was used to determine the depth to ground water	Not answered.
Did this release impact groundwater or surface water	Not answered.
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:	
A continuously flowing watercourse or any other significant watercourse	Not answered.
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Not answered.
An occupied permanent residence, school, hospital, institution, or church	Not answered.
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Not answered.
Any other fresh water well or spring	Not answered.
Incorporated municipal boundaries or a defined municipal fresh water well field	Not answered.
A wetland	Not answered.
A subsurface mine	Not answered.
An (non-karst) unstable area	Not answered.
Categorize the risk of this well / site being in a karst geology	Not answered.
A 100-year floodplain	Not answered.
Did the release impact areas not on an exploration, development, production, or storage site	Not answered.

Remediation Plan	
<i>Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.</i>	
Requesting a remediation plan approval with this submission	No
<i>The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.</i>	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 439778

CONDITIONS

Operator: CAZA OPERATING, LLC 200 N Loraine St Midland, TX 79701	OGRID: 249099
	Action Number: 439778
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By	Condition	Condition Date
nvez	None	3/6/2025