Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 449418

QUESTIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	449418
	Action Type:
	[NOTIFY] Notification Of Sampling (C-141N)

QUESTIONS

Prerequisites	
Incident ID (n#)	nRM2008547914
Incident Name	NRM2008547914 JONES D #001 @ 30-015-00192
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved
Incident Well	[30-015-00192] JONES D #001

Location of Release Source		
Site Name	JONES D #001	
Date Release Discovered	01/10/2020	
Surface Owner	Private	

Sampling Event General Information		
Please answer all the questions in this group.		
What is the sampling surface area in square feet	2,000	
What is the estimated number of samples that will be gathered	10	
Sampling date pursuant to Subparagraph (a) of Paragraph (1) of Subsection D of 19.15.29.12 NMAC	04/10/2025	
Time sampling will commence	08:00 AM	
Please provide any information necessary for observers to contact samplers	Angel Pena 575-605-0773	
Please provide any information necessary for navigation to sampling site	32.7506142,-104.3300247	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 449418

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	449418
	Action Type:
	[NOTIFY] Notification Of Sampling (C-141N)

CONDITIONS

Created By		Condition Date
apena	apena Failure to notify the OCD of sampling events including any changes in date/time per the requirements of 19.15.29.12.D.(1).(a) NMAC, may result in the remediation closure samples not being accepted.	