Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 459085

QUESTIONS

| Operator: | OGRID: |
|----------------------------|----------------------------------------------------|
| MATADOR PRODUCTION COMPANY | 228937 |
| One Lincoln Centre | Action Number: |
| Dallas, TX 75240 | 459085 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

QUESTIONS

| Prerequisites | |
|------------------|-------------------------------------|
| Incident ID (n#) | nAPP2512532447 |
| Incident Name | NAPP2512532447 DAGGER STATE SWD @ 0 |
| Incident Type | Produced Water Release |
| Incident Status | Initial C-141 Approved |

| Location of Release Source | |
|----------------------------|------------------|
| Site Name | Dagger State SWD |
| Date Release Discovered | 05/04/2025 |
| Surface Owner | State |

| Liner Inspection Event Information | | | |
|---------------------------------------------------------------------------------------------------------|---------------------|--|--|
| Please answer all the questions in this group. | | | |
| What is the liner inspection surface area in square feet | 4,914 | | |
| Have all the impacted materials been removed from the liner | Yes | | |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 05/09/2025 | | |
| Time liner inspection will commence | 09:00 AM | | |
| Please provide any information necessary for observers to liner inspection | Tank Containment | | |
| Please provide any information necessary for navigation to liner inspection site | 32.44961,-103.60718 | | |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 459085

CONDITIONS

| Operator: | OGRID: |
|----------------------------|----------------------------------------------------|
| · · | |
| MATADOR PRODUCTION COMPANY | 228937 |
| One Lincoln Centre | Action Number: |
| Dallas, TX 75240 | 459085 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Created By | | Condition Date |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| j_touchet | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 5/6/2025 |