Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 460124

QUESTIONS

| Operator: | OGRID: |
|--------------------|----------------------------------------------------|
| COG OPERATING LLC | 229137 |
| 600 W Illinois Ave | Action Number: |
| Midland, TX 79701 | 460124 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

QUESTIONS

| Prerequisites | s | |
|-------------------|-------------------------------------------|--|
| Incident ID (n#) | nAPP2512834713 | |
| Incident Name | NAPP2512834713 BANDANA 12G CTB @ 0 | |
| Incident Type | Release Other | |
| Incident Status | Initial C-141 Received | |
| Incident Facility | [fAPP2417645381] BANDANA FEDERAL 12 G CTB | |

| Location of Release Source | | |
|----------------------------|-----------------|--|
| Site Name | Bandana 12G CTB | |
| Date Release Discovered | 05/04/2025 | |
| Surface Owner | Private | |

| Liner Inspection Event Information | | | |
|---------------------------------------------------------------------------------------------------------|------------------------|--|--|
| ase answer all the questions in this group. | | | |
| What is the liner inspection surface area in square feet | 3,500 | | |
| Have all the impacted materials been removed from the liner | Yes | | |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 05/13/2025 | | |
| Time liner inspection will commence | 09:00 AM | | |
| Please provide any information necessary for observers to liner inspection | hgreen@ensolum.com | | |
| Please provide any information necessary for navigation to liner inspection site | 32.144244, -103.421802 | | |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 460124

CONDITIONS

| Operator: | OGRID: |
|--------------------|----------------------------------------------------|
| COG OPERATING LLC | 229137 |
| 600 W Illinois Ave | Action Number: |
| Midland, TX 79701 | 460124 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Create By | d Condition | Condition Date |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| jlair | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 5/8/2025 |