

Monthly Meter Analysis
April 2025

Meter #: T234040981
Name: TREBLE CTB SEPARATOR 3

Sample
Date:
Type:
Pressure: 200.0 H2O:
Temperature: 60.0 H2S:

Component	Mole %	Liquid Content	Mass %
Carbon Dioxide (CO2)	2.7066		5.3810
Nitrogen (N2)	2.1641		2.7386
Methane (C1)	73.9760		53.6113
Ethane (C2)	11.3709	3.0279	15.4457
Propane (C3)	6.0230	1.6522	11.9979
Isobutane (IC4)	0.7887	0.2570	2.0708
n-Butane (NC4)	1.7953	0.5636	4.7140
Isopentane (IC5)	0.4451	0.1621	1.4506
n-Pentane (NC5)	0.3999	0.1443	1.3033
Hexanes Plus (C6+)	0.3305	0.1353	1.2868
Argon (Ar)			
Carbon Monoxide (CO)			
Hydrogen (H2)			
Oxygen (O2)			
Helium (He)			
Water (H2O)			
Hydrogen Sulfide (H2S)			
Totals	100.0001	5.9424	100.0000

Property	Total Sample
Pressure Base	14.650
Temperature Base	60.00
Relative Density	0.7668
HV, Dry @ Base P,T	1234.44
HV, Sat @ Base P, T	1212.96
HV, Sat @ Sample P, T	1232.86
Cricondentherm	
HCDP @ Sample Pressure	
Full Wellstream	
Free Water	
Condensate	
26 # RVP Gasoline	0.643
Testcar Permian	0.657
Testcar Panhandle	0.614
Testcar Midcon	0.584

*** End of Report ***



Coterra Energy Inc.
Corporate Headquarters
Three Memorial City Plaza
840 Gessner Road
Suite 1400
Houston, TX 77024

T 281-589-4600
F 281-589-4955
coterra.com

Navigators:

Company

Search

Connections

Diagram

Route

Map

45908

Merrick ID

Name

45908

TREBLE CTB TANK FLARE

45908

TREBLE CTB TANK FLARE

Advanced Date Option: Start Date 4/15/2025 to End Date 5/12/25

Record Date	Gas Flowed	Hours Flowed	Meter Flare Reason	Static Pressure Psia	Differential Pressure	Meter Comments
5/6/2025	479.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2
5/5/2025	479.00	0	CURTAILMENT - GAS PURCHASER/HLP	0	0	vrus off due to high o2
5/4/2025	391.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2
5/3/2025	435.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2
5/2/2025	435.00	0	FACILITY ISSUES	0	0	vrus off due to high o2
5/1/2025	527.00	0	FACILITY ISSUES	0	0	vrus off due to high o2
4/30/2025	395.00	0	FACILITY ISSUES	0	0	vrus off due to high o2
4/29/2025	357.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2
4/28/2025	461.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2
4/27/2025	468.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2
4/26/2025	451.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2
4/25/2025	429.00	0	FACILITY COMPRESSION ISSUES	0	0	vrus off due to high o2

Intermediate flaring:

Event Date	Volume Flowed (mcf)	Duration (hrs)
4/26/2025	468	0.00

Details:

[331501] NORTHWIND MIDSTREAM PARTNERS LLC, Gas Quality Issue - Non-H2S, PURGING O2

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 462396

DEFINITIONS

Operator: Franklin Mountain Energy 3, LLC 6001 Deauville Blvd. Midland, TX 79706	OGRID: 331595
	Action Number: 462396
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 462396

QUESTIONS

Operator: Franklin Mountain Energy 3, LLC 6001 Deauville Blvd. Midland, TX 79706	OGRID: 331595
	Action Number: 462396
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	Unavailable.
Incident Facility	[fAPP2314257355] Treble CTB

Determination of Reporting Requirements <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	No
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas <i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	74
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	3
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 462396

QUESTIONS (continued)

Operator: Franklin Mountain Energy 3, LLC 6001 Deauville Blvd. Midland, TX 79706	OGRID: 331595
	Action Number: 462396
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	04/26/2025
Time vent or flare was discovered or commenced	12:00 AM
Time vent or flare was terminated	12:00 AM
Cumulative hours during this event	0

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Pipeline Quality Specifications Separator Natural Gas Flared Released: 468 Mcf Recovered: 0 Mcf Lost: 468 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	vrus off due to high O2
Steps taken to limit the duration and magnitude of vent or flare	MINIMIZE EVENT DURATION
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	PURGING O2

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 462396

ACKNOWLEDGMENTS

Operator: Franklin Mountain Energy 3, LLC 6001 Deauville Blvd. Midland, TX 79706	OGRID: 331595
	Action Number: 462396
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 462396

CONDITIONS

Operator: Franklin Mountain Energy 3, LLC 6001 Deauville Blvd. Midland, TX 79706	OGRID: 331595
	Action Number: 462396
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
jressling	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	5/14/2025