Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 465272

QUESTIONS

| Operator: | OGRID: |
|-------------------------------------|--|
| DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| 333 West Sheridan Ave. | Action Number: |
| Oklahoma City, OK 73102 | 465272 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

QUESTIONS

| Prerequisites | | |
|-------------------|------------------------------------|--|
| Incident ID (n#) | nAPP2511543162 | |
| Incident Name | NAPP2511543162 FLAGLER 8 CTB 3 @ 0 | |
| Incident Type | Produced Water Release | |
| Incident Status | Initial C-141 Approved | |
| Incident Facility | [fAPP2123646820] FLAGLER 8 CTB 3 | |

| Location of Release Source | | |
|----------------------------|-----------------|--|
| Site Name | FLAGLER 8 CTB 3 | |
| Date Release Discovered | 04/22/2025 | |
| Surface Owner | Federal | |

| Liner Inspection Event Information | | | |
|---|-----------------------------|--|--|
| Please answer all the questions in this group. | | | |
| What is the liner inspection surface area in square feet | 2,400 | | |
| Have all the impacted materials been removed from the liner | Yes | | |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 05/23/2025 | | |
| Time liner inspection will commence | 08:00 AM | | |
| Please provide any information necessary for observers to liner inspection | Kayla Taylor (432) 210-5443 | | |
| Please provide any information necessary for navigation to liner inspection site | 32.140726,-103.590823 | | |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 465272

CONDITIONS

| Operator: | OGRID: |
|-------------------------------------|--|
| DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| 333 West Sheridan Ave. | Action Number: |
| Oklahoma City, OK 73102 | 465272 |
| | Action Type: |
| | [NOTIFY] Notification Of Liner Inspection (C-141L) |

CONDITIONS

| Created By | | Condition Date |
|---------------|--|-------------------|
| jraley | Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted. | 5/20/2025 |